



Technical Service Bulletin

Technical Service Bulletin: TSB210159

Released Date: 27-Jul-2021

Accessory Drive Production Cleanness Improvement

Accessory Drive Production Cleanness Improvement

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM2350 K125
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K133
- QSK60 CM2350 K135
- QSK60 CM2350 K136
- QSK78 CM2250 K104
- QSK78 CM2350 K126
- QSK78 CM2350 K137

Description of Change

Manufacturing process changed from manual deburring to thermal deburring process to better remove any loose material from machining/broaching process.

Reason for Change

Accessory drive shaft material was found within the fuel pump. This change reduces the potential for material to be able to enter the oil flow.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Accessory Shaft	4916426	Yes	Yes	4924765
Accessory Shaft	-	-	-	5374289

The top-level part numbers of the Accessory Support assembly have **not** changed. Continue to order the below part numbers with the improved drive shaft included:

QSK38/50 Product:

- 4924764 - SUPPORT, ACCESSORY
- 4372986 - SUPPORT, ACCESSORY
- 5376112 - SUPPORT, ACCESSORY
- 5541921 - SUPPORT, ACCESSORY

QSK60/78 Product:

- 5375581 - SUPPORT, ACCESSORY
- 5375881 - SUPPORT, ACCESSORY
- 3647126 - SUPPORT, ACCESSORY
- 3650221 - SUPPORT, ACCESSORY
- 4381664 - SUPPORT, ACCESSORY
- 5372467 - SUPPORT, ACCESSORY
- 5374217 - SUPPORT, ACCESSORY
- 5416816 - SUPPORT, ACCESSORY
- 5538413 - SUPPORT, ACCESSORY
- 5540794 - SUPPORT, ACCESSORY
- 5541363 - SUPPORT, ACCESSORY
- 5541369 - SUPPORT, ACCESSORY

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

Part Number	ESN First	Build Date ¹	Plant
4924765	33223453	4 December 2020	Daventry Engine Plant
5374289	33223359	20 November 2020	Daventry Engine Plant

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2021-7-26	Module Created

Last Modified: 27-Jul-2021
