



Technical Service Bulletin

Technical Service Bulletin: TSB220018

Released Date: 10-Feb-2022

New Eliminator™ Lubricating Oil Filter Assembly

New Eliminator™ Lubricating Oil Filter Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- KV38 All
- KV50 All
- QSK38 All
- QSK45 All
- QSK50 All
- QSK60 All
- QSK78 All
- QSK95 All

Description of Change

New Eliminator™ Assemblies are being released with revised internals such as an improved hydraulic motor, centrifuge, and new filtering element screens which have a finer mesh screen to improve filtering capability.

Service Instructions

- The filter element screens are no longer purchased in pairs, all elements must now be replaced as a full assembly.
- The cleaning and inspecting procedure for the filter element screens is now **only** recommended in the case of a malfunction event or if in service cleaning is required.
- If damage is found to any of the existing element screens the recommended direction is to replace all filter elements with the new part number, although alternatively the damaged elements could be replaced with the existing part number. The new filter elements is **not** be mixed in with the existing part numbers.

Service Parts Availability

Service parts are available. See Tables 1 and 2 for part numbers.

Table 1, Service Parts New Eliminator™ Assembly				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Lubricating Oil Filter (QSK78 CM500)	3649467/5538155	Yes	Yes	5540795
Lubricating Oil Filter (QSK78 CM2350)	5538359	Yes	Yes	5540795
Lubricating Oil Filter (QSK60)	5372017	Yes	Yes	5540796
Lubricating Oil Filter (QSK60 CM2350)	5372167	Yes	Yes	5540796
Lubricating Oil Filter (QSK45)	5371886	Yes	Yes	5540797
Lubricating Oil Filter (QSK38/50)	5538131	Yes	Yes	5540798
With Filling Tube				
Lubricating Oil Filter (QSK38/50 CM2350) With Filling Tube	5538135	Yes	Yes	5540798
Table 2, Service Parts New Eliminator™ Element Screens				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Oil Filter Element	3393557	No	Yes	3651716
Part Compatibility New filter element screens are not to be mixed in with the existing part numbers, if new and existing screens are used together this can cause damage to the internals.				
Part Identification The filter element screens are only distinguishable by the pressed supplier part number 1800-03335 for the new screen and 1800-03336 on the old screens.				
Part Inventory Action Use existing part number inventory before using the new part number.				
Production Status Implemented for production. See Table 3.				

Table 3, Production Information			
ESN First	Build Date ¹	Plant	Shop Order
66305764 (QSK78)	24 April 2020	Daventry	SO11656
33221666 (QSK60)	19 May 2020	Daventry	SO10798
33221557 (QSK60 CM2350)	27 April 2020	Daventry	SO11807
ESN Last	Build Date ¹	Plant	Shop Order
33221517 (QSK45)	17 April 2020	Daventry	SO11947
¹ Engine build date can be found on the engine dataplate.			

Document History

Date	Details
2022-1-29	Module Created

Last Modified: 10-Feb-2022
