



Technical Service Bulletin

Technical Service Bulletin: TSB220121

Released Date: 09-Jun-2022

New Heat Shield Part Number

New Heat Shield Part Number

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK50 CM2150 MCRS

Description of Change

- Existing heat shields have been superseded with new designs of heat shields.
- The new designs have driven part number changes that are communicated in Table 1 below.

Reason for Change

Improvements have been made on the new designs to increase thermal containment efficiency and reduce the space claim of the heat shields.

Service Instructions

New part numbers **must** be fitted as a pair. See Part Compatibility section below for more information.

Service Parts

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Shield, Heat	3643681	Yes	Yes	5542292
Shield, Heat	3643682	Yes	Yes	5542293

Part Compatibility

- Do **not** mix existing and new part numbers.
- Example: 5542292 is designed to fit with 5542293 and will **not** fit with 3643682.
- The new parts together give full backwards compatibility to the overall heat shield assembly.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
33224989	1 June 2021	Daventry
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2022-6-8	Module Created