



Technical Service Bulletin

Technical Service Bulletin: TSB220212

Released Date: 18-Oct-2022

Industrial Low Temperature Aftercooler (LTA) Water Pump Repair Kits

Industrial Low Temperature Aftercooler (LTA) Water Pump Repair Kits

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552
- QST30 CM2350 T101
- QST30 CM2350 T103C

Description of Change

This document announces new LTA water pump repair kit part numbers.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Repair Kits for LTA Water Pump, Part Number 5409320

Part Number	Part Name
6389213	KIT,WATER PUMP REPAIR (MINOR)
6388354	KIT,WATER PUMP REPAIR (MAJOR)

Part Identification

- Table 2 documents a complete parts list for both repair kits and Figure 1 shows part location.
- Some parts within the LTA water pump, Part Number 5409320, are available for individual purchase. Reference Table 3 for a complete list.

Table 2, Parts List for Repair Kit, Part Numbers 6389213 and 6388354

Item Number in Figure 1	Name	Part Number 6389213	Part Number 6388354
1	LIPSEAL	1	1

Table 2, Parts List for Repair Kit, Part Numbers 6389213 and 6388354			
Item Number in Figure 1	Name	Part Number 6389213	Part Number 6388354
2	DEEP GROVE BALL BEARING	1	1
3	INTERNAL BEVELLED CIRCLIP	1	1
4	O RING	1	1
5	PUMP SHAFT	-	1
6	BALL BEARING	1	1
7	SHIM WASHER	1	1
8	LIPSEAL	1	1
9	O RING	1	1
10	O RING	1	1
11	SHAFT SLEEVE	1	1
12	MECHANICAL SEAL	1	1
13	CHEVRON IMPELLER	-	1
14	ORING	1	1
15	V CLAMP	2	2
16	GASKET	2	2

Table 3, Purchasable Parts Within LTA Water Pump	
Part Description	Part Number
SCREW, SOCKET HEAD CAP	4025372
WASHER, SPRING	4025373
SEAL, O RING	4025374
SEAL, O RING	4025376
CLAMP, V BAND	4025377
SEAL, WATER PUMP	4025378
SCREW, SOCKET HEAD CAP	5416040




Figure 1, LTA Water Pump.

Associated Publications

Table 4, Associated Publications

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QST30 CM552	4021539	Low-Temperature (LTA) Water Pump	Refer to Procedure 008-109 (/qs3/pubsy s2/xml/en/pr ocedures/57 /57-008-109.html)	8
Service Manual	QST30 CM2350 T101	5467179	Low-Temperature (LTA) Water Pump	Refer to Procedure 008-109 (/qs3/pubsy s2/xml/en/pr ocedures/36 3/363-008-109.html)	8

Table 4, Associated Publications					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QST30 CM2350 T103C	6309062	Low-Temperature (LTA) Water Pump	Refer to Procedure 008-109 (/qs3/pubsys2/xml/en/procedures/1085/1085-008-109.html)	8

Document History

Date	Details
2022-10-18	Module Created