



Technical Service Bulletin

Technical Service Bulletin: TSB230183

Released Date: 07-Nov-2023

New Rear Crankshaft Seal Part Number

New Rear Crankshaft Seal Part Number

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K38 (All versions)
- K50 (All versions)
- QSK38 (All versions)
- QSK50 (All versions)

Description of Change

- A new rear crankshaft seal has been released which has a larger outer diameter 214.12 mm [8.429 in] than the existing version 206.38 mm [8.125 in].
- Associated flywheel housings have also had part number changes to accommodate the larger diameter crankshaft seal.
- Service Tooling kit part numbers have been updated to accommodate the new design rear crankshaft seal.

Reason for Change

The new design of crankshaft seal and service tooling improves installation errors, lube oil sealing, and component longevity.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Housing, Flywheel	3176637	Yes	No	5374479
Housing, Flywheel	4917572	Yes	No	5374489

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Housing, Flywheel	3414620	Yes	No	5374494
Housing, Flywheel	4978338	Yes	No	5374498
Housing, Flywheel	3628045	Yes	No	5374483
Housing, Flywheel	3176637	Yes	No	5374479
Seal, Crank	3642365	No	No	4396606

Part Compatibility

- No backwards compatibility exists between part numbers in Table 1.
- Table 2 shows the part compatibility matrix.

Table 2, Part Compatibility Matrix		
Flywheel Housing	New Crankshaft Seal, Part Number 4396606 (214.12 mm [8.429 in] Diameter) Compatibility	Existing Crankshaft Seal, Part Number 3642365 (206.38 mm [8.125 in] Diameter) Compatibility
Flywheel Housing (214.12 mm [8.429 in] Bore)	Yes	No
Flywheel Housing (206.38 mm [8.125 in] Bore)	No	Yes

Part Inventory Action

- Use existing part number inventory before using the new part number.
- The existing crankshaft seal will remain available as the existing crankshaft seal is used on other engine configurations.

Service Tools and Training Available

The service tool kit has been updated to include parts that aid the installation of both existing and new crankshaft seals.

Production Status

Implemented for production. Reference Table 3.

Table 3, Production Information		
ESN First	Build Date ¹	Plant
33224419	31 March 2021	Daventry

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2023-9-15	Module Created

Last Modified: 07-Nov-2023
