



Technical Service Bulletin: TSB240023

Released Date: 29-Jan-2024

Fuel Shutoff Valve: External Fuel Leak

Fuel Shutoff Valve: External Fuel Leak

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552

Issue Summary

Symptom:

- External fuel leak from fuel shutoff valve shield

Root Cause:

- Fuel shutoff valve shield malfunction

Resolution

The fuel shutoff valve is a serviceable component. This malfunction can be repaired by replacing the fuel shutoff valve shield. See QST30 Service Manual. Refer to Procedure 005-043 (</qs3/pubsys2/xml/en/procedures/57/57-005-043-tr.html>) in Section 5 for replacement procedure.

Customer Communication

For customers experiencing frequent external fuel leaks from the fuel shutoff shield, customers should work with their local distributor or sales and services team to determine an appropriate interval to routinely replace both shutoff valve shields during planned downtime events.

Service Instructions

See QST30 Service Manual. Refer to Procedure 005-043 (</qs3/pubsys2/xml/en/procedures/57/57-005-043-tr.html>) in Section 5 for instructions on fuel shutoff valve disassembly and assembly. Figure 1 below identifies the fuel shutoff valve shield in the overall assembly.




Figure 1, Exploded View of Fuel Shutoff Valve Assembly.

- 1. Shutoff valve shield, Part Number 129839
- 2. Rectangular ring seal, Part Number 129888
- 3. Rectangular ring seal, Part Number 4975411

Service Parts

See Table 1 for minimum part numbers that will be needed at time of Shutoff Valve Shield replacement.

Table 1, Minimum Parts for Shutoff Valve Shield Maintenance Replacement (Per Engine)		
Part Description	Part Number	Quantity
Shutoff Valve Shield	129839	2 (1 per fuel shutoff valve)
Rectangular Ring Seal	129888	2 (1 per fuel shutoff valve)
Rectangular Ring Seal	4975411	2 (1 per fuel shutoff valve)

Document History

Date	Details
2024-1-29	Module Created

