



Technical Service Bulletin

Technical Service Bulletin: TSB240127

Released Date: 13-Jun-2024

New HE800 Turbocharger Bearing Housing Design

New HE800 Turbocharger Bearing Housing Design

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK45 (All Versions)
- QSK50 (All Versions)
- QSK60 (All Versions)

Description of Change

New HE800 turbochargers are being released with a new design of bearing housing which contains a coolant jacket for coolant cooling. This bearing housing has been designed so that the turbocharger can be used both wet and dry depending on if the engine has coolant plumbing already built in.

Service Instructions

If the turbocharger is going to be run dry, there will be no risk made by debris getting into the turbocharger as the coolant channel is completely sealed off from the turbocharger. Any debris that will enter the turbocharger will sit in a coolant channel. Do **not** block off any coolant ports as this could cause a heat trap and result in an overheated turbocharger.

Document History

Date	Details
2024-6-12	Module Created

Last Modified: 13-Jun-2024

