



Technical Service Bulletin

Technical Service Bulletin: TSB250197

Released Date: 16-Oct-2025

Lubricating Oil Suction Tube for Center-Deep, Industrial Application

Lubricating Oil Suction Tube for Center-Deep, Industrial Application

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552

Description of Change

For all QST30 CM552 Industrial applications, the **only** center-deep oil pan option available is OP5151, which includes lubricating oil suction tube bracket, Part Number 4310907. This is the most robust lubricating oil suction tube for the center-deep lubricating oil pan configuration for the QST30.

For any lubricating oil suction tube failures on Part Number 3093694 in the industrial application, replace with Part Number 4310907.

Reason for Change

This change is a result of lubricating oil suction tube failures with part number 3093694 within option OP5133.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Oil Suction Tube	3093694	No	No	4310907

Document History

Date	Details
2025-10-15	Module Created

Last Modified: 16-Oct-2025