

AT&T; Device Security Patch Bulletin (Synthetic Sample)

SYNTHETIC TRAINING DATA — fictional content created for a RAG demo. Not an actual AT&T; publication; device/model names are used only as realistic examples and do not reflect real vulnerabilities or patches.

Patch Number	Device Name	Model Number	Vuln. ID	Fix Description	Severity	Release Date
PATCH-AT-2024-045	AT&T; BGW210-700 Wi-Fi Gateway	BGW210-700	SEC-3477	Fixes an authentication bypass in the local admin web interface that allowed an attacker on the LAN to reach configuration pages without a password.	High	2024-03-05
PATCH-AT-2024-047	AT&T; BGW320-500 Wi-Fi Gateway	BGW320-500	SEC-3478	Fixes a remote authentication bypass in the admin web portal that allowed an unauthenticated user to change device configuration over the WAN interface.	Critical	2024-03-12
PATCH-AT-2024-048	AT&T; Arris NVG599 Gateway	NVG599	SEC-3479	Addresses an authentication bypass flaw in the remote management API that could let an attacker reset admin credentials without prior authentication.	Critical	2024-03-14
PATCH-AT-2024-050	AT&T; Fiber ONT Series 3000	ONT-3000	SEC-3480	Resolves a session fixation vulnerability in the admin portal login flow that could allow session hijacking after authentication.	Medium	2024-03-20
PATCH-AT-2023-091	AT&T; Pace 5268AC Gateway	5268AC	SEC-2201	Fixes a buffer overflow in the DHCP client that could lead to remote code execution when processing a malformed DHCP lease response.	Critical	2023-08-02
PATCH-AT-2023-093	AT&T; Arris NVG589 Gateway	NVG589	SEC-2203	Fixes a buffer overflow in the UPnP service that could crash the device or allow remote code execution via a crafted UPnP discovery packet.	Critical	2023-08-15
PATCH-AT-2023-094	AT&T; BGW210-700 Wi-Fi Gateway	BGW210-700	SEC-2204	Fixes a stack buffer overflow in the SIP ALG module triggered by an oversized SIP header during VoIP call setup.	High	2023-08-18
PATCH-AT-2024-012	AT&T; U-verse RG Router	3801HGV	SEC-2890	Fixes a reflected cross-site scripting (XSS) vulnerability in the diagnostics page that could execute attacker-supplied script in an admin's browser.	Medium	2024-01-10
PATCH-AT-2024-013	AT&T; BGW320-500 Wi-Fi Gateway	BGW320-500	SEC-2891	Fixes a stored cross-site scripting (XSS) vulnerability in the guest Wi-Fi network name field that could execute script when viewed by an admin.	Medium	2024-01-12
PATCH-AT-2024-014	AT&T; Fiber ONT Series 3000	ONT-3000	SEC-2892	Fixes a reflected XSS vulnerability in the firmware update status page reachable from the local network.	Low	2024-01-15
PATCH-AT-2022-077	AT&T; Pace 5268AC Gateway	5268AC	SEC-1650	Fixes a default/hardcoded credential issue in the Telnet debug service that was left enabled in certain firmware builds.	Critical	2022-11-03
PATCH-AT-2022-078	AT&T; Arris NVG599 Gateway	NVG599	SEC-1651	Removes a hardcoded backdoor account used during manufacturing that remained active in production firmware.	Critical	2022-11-05
PATCH-AT-2024-062	AT&T; Wireless Internet Gateway	AWI-2	SEC-3601	Fixes a denial-of-service condition where a malformed LTE control packet could repeatedly reboot the gateway.	High	2024-05-01
PATCH-AT-2024-063	AT&T; BGW320-500 Wi-Fi Gateway	BGW320-500	SEC-3602	Fixes a denial-of-service condition in the Wi-Fi driver triggered by a crafted 802.11 management frame.	High	2024-05-03
PATCH-AT-2021-034	AT&T; U-verse RG Router	3801HGV	SEC-0980	Fixes an insecure direct object reference (IDOR) in the parental controls API that allowed one household profile to modify another's settings.	Medium	2021-06-22
PATCH-AT-2021-035	AT&T; BGW210-700 Wi-Fi Gateway	BGW210-700	SEC-0981	Fixes weak WPS PIN generation that made the Wi-Fi Protected Setup PIN predictable and brute-forceable within a practical time window.	High	2021-06-25
PATCH-AT-2025-005	AT&T; Fiber ONT Series 3000	ONT-3000	SEC-3811	Fixes a path traversal vulnerability in the firmware backup/restore feature that could expose arbitrary files from the device filesystem.	High	2025-01-09
PATCH-AT-2025-006	AT&T; BGW320-500 Wi-Fi Gateway	BGW320-500	SEC-3812	Fixes a path traversal vulnerability in the diagnostics log export feature that could allow reading files outside the intended log directory.	Medium	2025-01-11

Patch Number	Device Name	Model Number	Vuln. ID	Fix Description	Severity	Release Date
PATCH-AT-2025-018	AT&T; Arris NVG599 Gateway	NVG599	SEC-3925	Fixes an unauthenticated firmware downgrade vulnerability that could allow an attacker to roll the device back to a version with known vulnerabilities.	High	2025-02-20
PATCH-AT-2025-019	AT&T; Pace 5268AC Gateway	5268AC	SEC-3926	Fixes an unauthenticated firmware downgrade vulnerability reachable from the WAN side under specific ISP provisioning configurations.	Critical	2025-02-22