22.02.2011 Date:	Z4 Quality Surveillance NCR					11006		
PO Number:	4500207141 REV.04							
Description:	Buoyancy Element - Label Issue 2							
PO Item:	NA							
Serial no:	B8000FT 610584 0009							
Action:	Corrected		Rework	Scrap		Doc		
	Yes	No X	yes					
Description of the fault:	The following observation was made on the 22.02.2011 during a scheduled inspection. Frigstadd Buoyancy Element stacked in Matrix Welshpool facility has deficient labels and do not conform to SOP 169. Under SOP 169, it has been classified as a B fault and should have been captured in MODMAN for Damaged Label due to the following: "Label not readable due to damage, heavy smudge, fade - need to be replaced" (Refer Fig: 4a, 4b) (see attached photograph below) There is a high likelihood of elements being released under Release 12 having this label issue still outstanding due to lack of visual advantage. NCR Z4-11006 has been raised to capture this concern.							
Fault cause:	Vendor			Aker Solutions				
	MATRIX							
QS Inspector:	206596		vincent.cheong@akersolutions.com					
Hired-In insp.:			na					
Coordinator:	206622		sritharan.pillay@akersolutions.com					

Follow up actions: Attention HaydnL@matrixap.com.au - Matrix

Line	Required actions	Category	Responsible person	Signed
1	Please investigate	urgent	Haydn	
2	Provide records to show this fault is captured on MODMAN as specified in SOP169	urgent	Haydn	
3	AS Australia to be advised upon completion via return of this Z4 NCR	urgent	Haydn	



