

1. CUSTOMER & INCIDENT ORIGIN

Customer Name:	ABC Formulations Ltd.	Complaint Date:	12 August 2026
Facility Location:	Plant-2, API Receiving Bay, Hyderabad	Source / Mode:	Email / QC Inspection Report
Contact Person:	Dr. S. K. Nambiar (Head - QA)	Current Status:	PENDING TRIAGE

2. PRODUCT & BATCH IDENTIFICATION

Product Name:	Metformin Hydrochloride API	Grade / Spec:	IP / BP / Ph. Eur.
Batch / Lot No:	CHG 260712A	Affected Quantity:	50 kg (2 HDPE Drums)
Mfg Date:	25 June 2026	Expiry Date:	24 June 2031
GRN / Receipt No:	GRN-2026-8841	Storage Condition:	Store below 25°C, Dry Area

3. DETAILED COMPLAINT DESCRIPTION & FINDINGS

Defect Category: Foreign Matter Contamination (Class I Defect Risk)

Incident Summary:

During routine incoming quality control sampling and raw material verification inside the ISO Class 8 sampling booth at ABC Formulations Ltd., laboratory analysts reported multiple dark foreign particles embedded near the upper surface of the powder inside one sealed 25 kg HDPE drum (Drum #1 of Batch CHG 260712A).

Both drums under GRN-2026-8841 were received with unbroken tamper-evident seals intact, indicating that the foreign particulate contamination was likely introduced prior to or during primary packaging at the bulk manufacturing site. Sampling was immediately suspended, and the entire consignment of 50 kg was placed on QA Material Hold.

4. PRELIMINARY QC INSPECTION RESULTS

TEST PARAMETER	SPECIFICATION LIMIT	OBSERVED RESULT	COMPLIANCE
Visual Appearance	White crystalline, odorless powder	Dark particles observed	FAIL
Particle Isolation	No visible foreign matter	0.5mm – 1.8mm black fibers/specks	FAIL
Identification (FTIR)	Conforms to Reference Standard	Conforms to Metformin HCl	PASS
Assay (Titrimetric)	98.5% – 101.0% (Dry basis)	99.6% w/w	PASS

5. INITIAL AI COPILOT & QA RISK ASSESSMENT

Assessed
Severity:

CRITICAL

Action Required: Immediate RMA & Replacement

Critical Risk Flag: Foreign particulate contamination in API poses direct risks to final dosage form stability, blend uniformity, and regulatory compliance. Potential root causes include drying equipment gasket erosion, sifter screen mesh damage, or environmental exposure during drum filling.

6. CUSTOMER ACTION REQUESTED

- Issue formal acknowledgement of complaint reference **CC-2026-00154**.
- Dispatch an urgent replacement shipment of **50 kg Metformin Hydrochloride API** (Fresh Batch).
- Provide Return Material Authorization (RMA) instructions for returning the affected batch **CHG 260712A**.
- Submit full 8D Root Cause Analysis (RCA) and Corrective & Preventive Action (CAPA) report within 14 business days.

7. AUTHORIZATION & QA SIGN-OFF

REPORTED BY (QC ANALYST)

R. V. Sharma
Senior QC Officer

Date: 12-Aug-2026 | Time: 10:15 AM

REVIEWED BY (QA MANAGER)

Dr. S. K. Nambiar
Head - Quality Assurance

Date: 12-Aug-2026 | Time: 11:30 AM

QMS ENTRY SYSTEM

AIVOA QMS Copilot
Automated Intake Engine v2.4

Status: Ready for QMS Commit