
Ideal command
Noisy updates
With gap
Held command near gap
Angle (deg)
25
20
15
Error (deg)
5
0
−5
Clean
With gap
Gap effect (deg)
1
0
0
1
2
3
4
5
6
7
8
9
10
Time (s)