

TitanForge ZX-440 Service Manual — Rev 6

Document Control

Status: CURRENT

Effective: 01 July 2026

Models: ZX-440, ZX-440A

E117 — Pressure Sensor Validation

E117 indicates that the pressure-sensor validation sequence failed after replacement or calibration. Confirm connector seating, verify sensor calibration range, and compare live pressure against the reference channel. Do not bypass the safety interlock.

Warning

WARNING: The interlock must remain enabled during E117 diagnosis. If the equipment falls within an active safety-bulletin serial range, the bulletin takes precedence over this manual.

Valve Assembly Table

Compatibility is exact by model variant.

Model	Valve Assembly	Notes
ZX-440	VA-440-22	Standard
ZX-440A	VA-440A-31	Not interchangeable with VA-440-22