

SAHYADRI PETROCHEMICALS LTD.	Doc No: SPL-COMP-REF-008
Compliance Cell, Refinery Division	Rev: 2 Date: 15-Dec-2024
Classification: INTERNAL	Page 1 of 1

REGULATORY COMPLIANCE REFERENCE

Statutory requirements — Hydrocarbon Rotating Equipment

Summary of statutory and standard requirements applicable to hydrocarbon pumping equipment such as P-1101A, maintained by the Compliance Cell. Original notifications are held across email and the regulatory archive.

Applicable Requirements

Reference	Requirement (summary)	Frequency
OISD-STD-119, Cl. 5.3	Rotating equipment in hydrocarbon service shall have a documented predictive-maintenance / vibration monitoring programme; corrective action records shall be maintained and auditable.	Continuous
OISD-STD-119, Cl. 7.2	Repeat failures of the same equipment shall trigger a documented Root Cause Failure Analysis (RCFA).	On repeat failure
Factory Act 1948, S.41B	Major-accident-hazard sites shall maintain hazard control and incident records demonstrating action on identified risks.	Continuous
Petroleum Rules / PESO	Equipment handling flammable petroleum shall be maintained to prevent leakage; leakage events to be recorded and addressed.	Continuous

Compliance Observation

For P-1101A, vibration monitoring data exists (CM cell) and three repeat seal failures are recorded in the CMMS, but **no documented RCFA has been raised** as required by OISD-STD-119 Cl. 7.2, and the corrective-action trail is fragmented across maintenance, reliability and HSE systems. This represents an open compliance gap.

Maintained by: Compliance Cell | Inspector of record: P. Nair