
Schema di collegamento - Connection diagram - Schemas de branchement - Schaltplan - Esquemas de conexiòn




Motori trifase due velocità, un avvolgimento — *Three phase motors two speeds, one winding* — Moteurs triphasé deux vitesses, un enroulement — *Drehstrommotor zwei Drehzahlstufen, eine Wicklung* — Motores trifásico dos velocidades, un bobinado

Motors

Collegamento alta velocità - Connection high speed - Connexion grande vitesse - Schaltung Hohe Drehzahl - Conexiòn alta velocidad



Collegamento bassa velocità - Connection low speed - Connexion petite vitesse - Schaltung Niedrige Drehzahl - Conexiòn baja velocidad



L1 - L2 - L3 = Linea - Supply - Reseau - Netz - Red

Per invertire la rotazione invertire due fasi - *To change the rotation reverse two phases* - Pour changer le sens de rotation inverser deux phases - *Zur Drehrichtungsänderung zwei Phasen vertauschen* - Para invertir el sentido de rotación invertir dos fases