
Schema di collegamento - Connection diagram Schemas de branchement - Schaltplän Esquemas de conéxiòn




DTE 01/01/2004 SC - 01 - T - 1v.doc

Motori trifase una velocità - *Single speed, three phase motors* - Moteurs triphasé une vitesse *Drehstrommotor Eine Drehzahlstufe* - Motores trifásico una velocidad

Collegamento - Connection - Connexion - Schaltung - Conexión



Collegamento - Connection - Connexion - Schaltung - Conexión



L1 - L2 - L3 = Linea - Supply - Reseau - Netz - Red

Per invertire la rotazione invertire due fasi - To change the rotation reverse two phases - Pour changer le sens de rotation inverser deux phases - Zur Drehrichtungsänderung zwei Phasen vertauschen - Para invertir el sentido de rotación invertir dos fases