
Schema di collegamento - Connection diagram - Schemas de branchement - Schaltplan - Esquemas de conexiòn




Motors

Motori trifase due velocità, due avvolgimenti - *Three phase motors, two speeds, two windings* - Moteurs triphasé deux vitesses, deux enroulements - *Drehstrommotor zwei Drehzahlstufen, zwei Wicklungen* - Motores trifásico dos *velocidades*, dos bobinados

Collegamento alta velocità - Connection high speed - Connexion grande vitesse - Schaltung Hohe Drehzahl - Conexiòn alta velocidad



Collegamento bassa velocità - Connection low speed - Connexion petite vitesse - Schaltung Niedrige Drehzahl - Conexiòn baja velocidad



L1 - L2 - L3 = Linea - Supply - Reseau - Netz - Red

Per invertire la rotazione invertire due fasi - *To change the rotation reverse two phases* - Pour changer le sens de rotation inverser deux phases - *Zur Drehrichtungsänderung zwei Phasen vertauschen* - Para invertir el sentido de rotación invertir dos fases