File	Serial Number W/ Production Number	Original Symptoms	Standardized Symptoms
records_AdamBerges.pdf	SLLV42sc-463	 Unresponsive Linear Stage Piezo damage, likely from Feb 5th power outage 	- Unresponsive, Piezo Damage
records_AnthonyFong.pdf	STT50.8v-6	- Cable damaged	- Cable Damage
records_AnthonyFong.pdf	SR70121-18	- Piezo burned, replace piezo drive	- Piezo Damage
records_AnthonyFong.pdf	STT25.4v-25	- Piezo burned, need to manufacture a new STT-25.4-VE	- Piezo Damage
records_AdamBerges.pdf	SLC2445ds-?	- Stage would fail sporadically in closed-loop movements including "homing" - Wrong positioner type assigned – also had a sensor type conflict with neighboring stages on the sensor module. Rearranged cabling & assignments to keep all L-type and S-type stages with compatible types	- Inaccurate Motion, Inaccurate Motion
records_AdamBerges.pdf	SLC1740ds-85	 Unresponsive, hanging after sticky movements Piezo damaged. Possible user error, stage could be run indefinitely into the EJX enclosure 	- Unresponsive, Inaccurate Motion, Piezo Damage
records_AdamBerges.pdf	SLLV42lc-473	 Unresponsive movement Piezo damage. Very unexpected, as the stage was powered off for approximately 1 month before this failure occurred, as EJX controls were disabled during OPA install 	- Inaccurate Motion, Unresponsive, Piezo Damage