Comment	Designator	Footprint	LCSC Part No	Manuf. Part No	Comment
USB micro connector	CON1, CON2		C719023	ZX62D-B-5P8(30)	
	SW1,SW2		C445493	K2-1102DP-L3SW-04	
	SW3		C2887259	SS12D10G4 071	
	C9,C12,C13,C15,C16,C17,C19,C20	0603	C66501	CC0603KRX7R9BB104	
	C1,C2,C3,C4,C5,C6,C7,C8,C10,C11,C18		C5672	CL31A226KPHNNNE	
<u> </u>	C14		C19702	CL10A106KP8NNNC	
	REG1	DFN-8-EP(2x2)		TPS62082DSGR	
	L1	, ,	C2913752	BDHH002016101R0MDB	datasheet of REG1 recommends XFL3012-102MEB, but that is not available in JLCPCB library
MOSFET	Q2,Q3,Q4	SOT-23	C400505	BSS138	
3K92 1%	R8	0603	C170585	WR06X3921FTL	
680R 1%	R11, R16	0603	C23228	0603WAF6800T5E	
430R 1%	R14	0603	C23170	0603WAF4300T5E	
1K 1%	R1,R5,R6,R9	0603	C21190	0603WAF1001T5E	
220R 1%	R3	0603	C22962	0603WAF2200T5E	
	R10		C22843	0603WAF1501T5E	
3K 1%	R12	0603	C4211	0603WAF3001T5E	
100K 1%	R23	0603	C25803	0603WAF1003T5E	
100R F	R2,R19,R22	0603		0603WAF1000T5E	
	R4	0603		0603WAF3000T5E	
	R20,R27	0603		0603WAF3301T5E	
	R13	0603	C22827	0603WAF1803T5E	
	R26	0603		CR0603FA1541G	
	R7	0603		0603WAF1002T5E	
	•••				
Shotky diode	D5, D8	SOT-23	C37704	BAT54C,215	
-	U2	SOT-23-3		TL431A PJSEMI	warning: original TI part has diferent pinout!
	U1	SOT-25-5		AP331AWG-7	g g g p p p p p p p p
· ·	JX1,JX2		C2764776	61083-101400LF	
level shifter	U3,U4	TSSOP-20	C53406	TXB0108PWR	
	R25		C2097544	MCT06030C4871FP500	for green 5V indicator LED
PL LED yellow	D1,D2		C2296	17-21SUYC/TR8	
	R17,R18		C22808	0603WAF1500T5E	for yellow 3.3V indicator LED
	,				, , , , , , , , , , , , , , , , , , , ,
±0.5ppm 50MHz oscillator	X1		C2920832	NT0503DH3I507BN50	
Interface Chip USB/UART	U5	SOP-16	<u>C14267</u>	CH340G	the same as used in https://www.sparkfun.com/products/14050
AND gate	U6	X1-DFN1010-6	C150443	74LVC1G08FW5-7	, , , , , , , , , , , , , , , , , , ,
0	Y1	SMD2520-4P		2TJ412000UYGBC	
-1 7	C21,C22		C881987	C0402C0G220J250NTB	
	D3,D4,D6		C2833058	BZ-C0603-G3-F1	power indicators, RX to FPGA
	R15		C4326496	CRCW0402133RFKED	Pr
	D7	0603		A-SP192YY3C-A01-4T	
·	R24		C365385	ETCR0603F154RK9	

Following connectors are not part of BOM, i.e. not part of JLCPCB Assembly (they are intended for DYI hand soldering):

Comment	Designator	Manuf. Part No
38 pin header	J4	SSW-119-01-F-D
52 pin header	J3	SSQ-126-03-G-D
2 pin header, 6 mm	JP1	<u>61300211121</u>
PMOD receptacle right angle	PMODH1,PMODH2,PMODH3	SSQ-106-03-T-D-RA
PMOD receptacle straight	PMODV1,PMODV2,PMODV3	Farnell SSQ-106-01-G-D
Power connector 8 pin, 2 rows	J5,J6	Farnell SSQ-104-02-G-D
GND header for probes, 4 pin, 1 row	J2, J7	Farnell TSW-104-14-L-S