RIVERBANK · STEERING GROUP DECISION

The pilot supports another measurement cycle—not wider installation yet.

RECOMMENDED NEXT STEP

Authorize one more measurement cycle.


The pilot shows a positive yield signal, with mixed plot results and important limits on interpretation.

BEFORE WIDER INSTALLATION

Measure installation cost and energy use; neither was assessed in this pilot.

MEDIAN YIELD DIFFERENCE **+6%**

Versus each site's reference plots · individual plot differences ranged −3% to +14%



12 of 18 plots positive

6 plots did not have a positive difference

INTERPRET WITH CARE

Not randomly assigned; crop mix and baseline conditions differed by site. Observed differences do not establish that lighting caused them.

18 plots · 3 sites · one winter growing cycle