HOME RETROFIT FEEDBACK · PROGRAM LEADS

Which barrier is most common overall—and did turnaround improve?

Neither can be answered from these summaries. Both point to installer delays, but there is no compatible overall comparison or comparable turnaround baseline.

PARTNER NORTH · HOMEOWNER SURVEY

28 of 40

selected installer scheduling; respondents could select multiple barriers

Upfront cost	**17 of 40**
Unclear eligibility	**9 of 40**

Selections overlap. These counts describe North's survey only.

PARTNER SOUTH · OPEN CASE REVIEW

9 of 15 cases

mentioned "waiting for an installer"

Homeowners served	**not reported**
Other barriers	**not recorded**

Cases are not a reported homeowner denominator; do not compare or pool with North.

SERVICE TURNAROUND

8 days median

for 11 of 15 South cases; 4 had no time recorded

"Around two weeks last spring" has no identified cases, sample size, or method. It is not a comparable baseline, so improvement is unknown.

TO IDENTIFY THE LEADING BARRIER

Use a shared period and barrier question, consistent coding, and a common denominator; define how multiple selections are counted.

TO ASSESS IMPROVEMENT

Collect recent and baseline turnaround with the **same method, period definition, and case scope**, plus the number of cases and missing-time counts.