## **Interrupt Assignment**

- 1. WAP to enable two interrupts, Turn ON LED through one interrupt and TURN OFF LED through another interrupt.
- 2. WAP to Blink LED in an ISR with the delay of 2000 ms.
- 3. WAP to take a number(delay) from UART through interrupt and blink the led using that number(delay).