

FYP-LOGISTICS / PLC_1 [CPU 1214C DC/DC/Rly] / Program blocks

Block_2 [FB2]

Block_2 Properties							
General							
Name	Block_2	Number	2	Type	FB	Language	SCL
Numbering	Automatic						
Information							
Title		Author		Comment		Family	
Version	0.1	User-defined ID					

Block_2									
Name	Data type	Default value	Retain	Accessible from HMI/OPC UA/Web API	Writ-able from HMI/ OPC UA/ Web API	Visible in HMI engi-neering	Setpoint	Supervi-sion	Comment
Input									
Output									
InOut									
▼ Static									
MaxValueDataReady	Bool	false	Non-retain	True	True	True	False		
MaxValue	Word	16#0	Non-retain	True	True	True	False		
SamplingActive	Bool	false	Non-retain	True	True	True	False		
FinSampleIndex	Int	0	Non-retain	True	True	True	False		
▼ Temp									
checkIndex	Int								
Constant									

```
0001 IF "P_Sensor1_TP" THEN
0002     #SamplingActive := TRUE;
0003 END_IF;
0004
0005 IF "reset_queue" THEN
0006     #SamplingActive := FALSE;
0007 END_IF;
0008
0009 IF #SamplingActive THEN
0010     #MaxValueDataReady := FALSE;
0011     IF "sample_index".CV < 1000 THEN
0012         "BUFF".Weight_Samples["sample_index".CV] := "BUFF".DATA[0];
0013         IF NOT "reset_queue" THEN
0014             #FinSampleIndex := "sample_index".CV;
0015         END_IF;
0016     ELSE
0017         #SamplingActive := FALSE;
0018     END_IF;
0019 ELSE
0020     #MaxValue := "BUFF".Weight_Samples[0];
0021     FOR #checkIndex := 0 TO #FinSampleIndex DO
0022         IF "BUFF".Weight_Samples[#checkIndex] > #MaxValue THEN
0023             #MaxValue := "BUFF".Weight_Samples[#checkIndex];
0024         END_IF;
0025     END_FOR;
0026     #MaxValueDataReady := TRUE;
0027 END_IF;
0028
```

Symbol	Address	Type	Comment
"BUFF".DATA[0]		Word	
"BUFF".Weight_Samples[0]		Word	
"BUFF".Weight_Samples[*]		Word	
"P_Sensor1_TP"	%M5.3	Bool	
"reset_queue"	%M5.6	Bool	
"sample_index".CV		Int	
#checkIndex		Int	
#FinSampleIndex		Int	
#MaxValue		Word	
#MaxValueDataReady		Bool	
#SamplingActive		Bool	