

Explanation of Robot Controller Schematic

This document explains a schematic diagram for a circuit that appears to be part of a robot controller project.

The main component in the schematic is the QMC5883L, which is a 3-axis magnetic sensor typically used for compass

or orientation sensing in robotics and embedded systems.

Key Features of the Schematic:

1. QMC5883L Sensor (U8):

- The sensor is connected to power (3.3V) and ground (GND).
- Its key pins, including SDA (data line) and SCL (clock line), are connected to an I2C bus for communication

with a microcontroller or other devices.

2. Capacitors (C29, C30, C31, C32):

- Decoupling capacitors are used near the power pins (VDD and GND) to stabilize the power supply and reduce noise.
 - C31 (0.1 μF): Typical bypass capacitor for VDD.
 - C29 (0.1 μF): Another decoupling capacitor on the I2C lines.
 - C30 (0.22 µF): Used for SETP (Set Point) pin stabilization.
 - C32 (4.7 μF): Provides bulk decoupling for power lines.

3. Pin Connections:

- The schematic shows clear connections for the SDA, SCL, SETP, and SETC pins.

- Unused pins are labeled as "NC" (No Connection).

4. I2C Interface:

- The SDA and SCL lines facilitate communication with other components using the I2C protocol.

5. Project Details:

- Title: Robot Controller v1.0

- Author: Ruchira Thilan Munasinghe

- Company: Orise (Pvt) Ltd, based in Sri Lanka.

- Date: 27th June 2023.

6. Purpose of the Circuit:

- This circuit is designed to integrate the QMC5883L sensor into a robot controller, enabling magnetic field sensing

for orientation, navigation, or motion tracking.