


Dial-Type 3D Joint Meter

Displacement & Settlement Monitoring | Product brochure

Dial Gauge Type 3D Joint Meter



3D joint meter with three dial gauges for measuring movement at expansion joints and cracks.

Key benefits

- Triple dial gauge monitoring
- Measures joint and crack movement
- Customizable mounting system

Engineering highlights

3D movement tracking: Monitors expansion joint displacement in three directions.

Dial gauge clarity: Easy-to-read mechanical indicators.

Installation flexibility: Customizable for dam, tunnel and tank applications.

Typical applications

- Joint displacement
- Crack movement
- Dam and tunnel monitoring

Technical specifications

Specification	Value
---------------	-------

Sensors	3 dial gauges
Measurement	Triple axial movement
Use	Expansion joint monitoring

Contact: info@gim-nextgen.com | +91 98765 43210 | Mumbai, India

Updated brochure generated on May 02, 2026