

IP Distress Alarm Issues - 18 May 2026 - Customer Email

Sl. No.	Location	Problem Description	Remarks
1	SGR	Video Call Not Operational	
2	WT-40	Video Call Not Operational	
3	WT-34	Video Call Not Operational	
4	WT-12	Video Call Not Operational	
5	WT-01	Manual Alarm Button Not Operational	
6	WT-02	Manual Alarm Button Not Operational	
7	WT-06	Manual Alarm Button Not Operational	
8	WT-07	Manual Alarm Button Not Operational	
9	WT-08	All Hooter Alarm Button Not Operational	
10	WT-13	Manual Alarm Button Not Operational	
11	WT-14	Manual Alarm Button Not Operational	
12	WT-15	All Hooter Alarm Button Not Operational	
13	WT-26	All Hooter Alarm Button Not Operational	
14	WT-29	Manual Alarm Button Not Operational	
15	WT-31	Manual Alarm Button Not Operational	
16	WT-35	Manual Alarm Button Not Operational	
17	NORA GATE	All Hooter Alarm Button Not Operational	
18	WT-39	Manual Alarm Button Not Operational	