Hidden measurement audits: detection and blind spots



n=1536 test phantoms per point; Wilson intervals conditional on shared fitted model/calibration.