



11/19

Mock demo today. Mostly everything was operational however the main problems were refining the physical build since there's wires every where and the humidity and i2c bus broke down part way through. Most systems are operational.



Wire sheathing is bought

11/20

Our I2C has been having issues for a while now, so to fix this I bought and resoldered our humidity sensors

This seemed to be a fix, the last humidity sensor may have been cooked from soldering and resoldering too often

11/24

The physical build is completed, we added wire sheathing and also mounted the device onto a board. In addition a box was

We spent a while trying to figure out how to build the shade. This turned out to be a failure since our stepper was too weak

We found it was a testing 1oz in which can't even overcome the shade fabric from running over a sharp edge. So we canned it since we are spending too much time on it.