Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: Antilia

Inspection Date: 2024-09-18
Inspector Name: Lucky Mosby

1. Inspection Summary

This inspection revealed significant fire safety concerns at Antilia. While fire extinguishers are pre-

2. Detailed Findings

Fire Extinguishers:

Present: Yes

Condition: Expired

• Comments: All fire extinguishers present were found to be expired. Expired fire extinguishers at

Fire Alarm System:

Condition: Not Present

Comments: No fire alarm system was found during the inspection. A functional fire alarm syster

Exits:

- Overall Condition: 3 (Potential Issues)
- Comments: The condition of exits needs further investigation. Specific concerns include:
 - [List specific concerns about exit conditions observed, e.g., blocked pathways, inadequate light

3. Risk Assessment

The absence of a functional fire alarm system and expired fire extinguishers creates a high risk of

4. Next Steps

The following actions are urgently required to address the fire safety deficiencies identified: