Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: Omniwas Apartment

Inspection Date: 2024-09-06

Inspector Name: vsv

1. Inspection Summary

This inspection revealed several critical fire safety deficiencies at Omniwas Apartment. While fire

2. Detailed Findings

Fire Extinguishers:

Present: Yes

Condition: Expired and pressure not properly maintained

• Comments: The fire extinguishers are currently unusable due to their expired status and improp

Fire Alarm System:

Condition: Functional

Comments: The fire alarm system was functional during the inspection. However, it was not pre

Exits:

• Condition: 3

Comments: The overall condition of exits was deemed satisfactory.

3. Risk Assessment

The following risks have been identified:

- High Risk: Expired and improperly maintained fire extinguishers present a significant risk of beir
- High Risk: The lack of a functioning fire alarm system during a recent emergency situation pose
- Moderate Risk: While the overall condition of exits was deemed satisfactory, a detailed inspecti