First Information Report (FIR) Summary

Report Number: FIR2024001

Date of Report: 2024-10-25

Police Station: MG Road Police Station, New Delhi

Complainant Details

| Name | Rohit Sharma |
|---------|------------------|
| Address | Sector 15, Noida |
| Contact | +91 9876543210 |

Accident Details

| Date and Time | 2024-10-24 18:30 |
|-------------------|--------------------------|
| Location | Near City Mall, MG Road |
| Туре | Collision |
| Vehicle | Hyundai i20 (DL8CAF1234) |
| Driver License | DL123456789 |
| Driver Age/Gender | 32 / Male |

Injury/Damage Details

| Injuries | Minor injuries to the complainant |
|-----------------|-----------------------------------|
| Property Damage | Front bumper damage |

Witness Information

| Name | Arjun Kapoor |
|---------|----------------|
| Contact | +91 9988776655 |

Narrative Summary

The investigation revealed that Mr. Sharma was driving at a speed of approximately 50 km/h when another vehicle suddenly appeared from an adjoining street. In an attempt to avoid a collision, Mr. Sharma swerved his vehicle, leading to a minor collision with a nearby tree. Skid marks and the vehicle's damaged front bumper confirm the abrupt turn. Witness accounts further support that the other vehicle was driven recklessly. No CCTV footage was available at the location, and further

action is pending to locate the other vehicle involved.

Officer Details

| Name | Inspector Vijay Kumar |
|-------|-----------------------|
| Badge | INSP-007 |

Vehicle Repair Cost Estimates

Estimate for FIR: FIR2024001

| Vehicle | Hyundai i20 |
|--------------|-------------|
| Registration | DL8CAF1234 |

Repair Details

| Repair Item | Parts Cost (■) | Labor Hours | Labor Cost (■) |
|------------------------------------|----------------|-------------|----------------|
| Front bumper replacement and paint | 12,000.00 | 3 | 1,500.00 |
| Wheel alignment | 1,000.00 | 1 | 500.00 |

Cost Summary

| Parts Cost | ■ 13,000.00 |
|------------|--------------------|
| Labor Cost | ■ 2,000.00 |
| GST (18%) | ■ 2,700.00 |
| Total Cost | ■ 17,700.00 |

Disclaimer: This is an estimated cost based on standard repair rates. Actual costs may vary depending on the exact extent of damage, parts availability, and additional damage discovered during repairs. All prices include standard parts and labor charges. Additional charges may apply for premium/imported parts.