First Information Report (FIR) Summary

Report Number: FIR2024001

Date of Report: 2024-10-25

Police Station: MG Road Police Station, New Delhi

Complainant Details

Name	Rohit Sharma
Address	Sector 15, Noida
Contact	+91 9876543210

Accident Details

Date and Time	2024-10-24 18:30
Location	Near City Mall, MG Road
Туре	Collision
Vehicle	Hyundai i20 (DL8CAF1234)
Driver License	DL123456789
Driver Age/Gender	32 / Male

Injury/Damage Details

Injuries	Minor injuries to the complainant
Property Damage	Front bumper damage

Witness Information

Name	Arjun Kapoor
Contact	+91 9988776655

Narrative Summary

The investigation revealed that Mr. Sharma was driving at a speed of approximately 50 km/h when another vehicle suddenly appeared from an adjoining street. In an attempt to avoid a collision, Mr. Sharma swerved his vehicle, leading to a minor collision with a nearby tree. Skid marks and the vehicle's damaged front bumper confirm the abrupt turn. Witness accounts further support that the other vehicle was driven recklessly. No CCTV footage was available at the location, and further

action is pending to locate the other vehicle involved.

Officer Details

Name	Inspector Vijay Kumar
Badge	INSP-007

Vehicle Repair Cost Estimates

Estimate for FIR: FIR2024001

Vehicle	Hyundai i20
Registration	DL8CAF1234

Repair Details

Repair Item	Parts Cost (■)	Labor Hours	Labor Cost (■)
Front bumper replacement and paint	12,000.00	3	1,500.00
Wheel alignment	1,000.00	1	500.00

Cost Summary

Parts Cost	■ 13,000.00
Labor Cost	■ 2,000.00
GST (18%)	■ 2,700.00
Total Cost	■ 17,700.00

Disclaimer: This is an estimated cost based on standard repair rates. Actual costs may vary depending on the exact extent of damage, parts availability, and additional damage discovered during repairs. All prices include standard parts and labor charges. Additional charges may apply for premium/imported parts.

Estimate for FIR: FIR2024004

Vehicle	Toyota Corolla
Registration	KA03AB5678

Repair Details

Repair Item	Parts Cost (■)	Labor Hours	Labor Cost (■)
Major dent repair and paint	8,000.00	4	2,000.00
Door repair and paint	15,000.00	3	1,500.00

Cost Summary

Parts Cost	■ 23,000.00
Labor Cost	■ 3,500.00
GST (18%)	4 ,770.00
Total Cost	■ 31,270.00

Disclaimer: This is an estimated cost based on standard repair rates. Actual costs may vary depending on the exact extent of damage, parts availability, and additional damage discovered during repairs. All prices include standard parts and labor charges. Additional charges may apply for premium/imported parts.