				<u> </u>										
SERVICE CALL REPORT - Exception Report									NUMERIC					
Head Office: 10th Floor, Pre	esige C	entre	Court, C	Office Blo	ck, Vijaya Forum Mall, 183, N.S.K Sala	i, Vadapa	lani, Chennai, Tamili	nadu-60	0026					
Customer Support Number	er - 048	4 3103	3266 / 04	484 4723	3266 : Support email id : customer.care	@numerio	cups.com					A Group brand	Li legrar	na
CUSTOMER NAME & ADDRESS: STATE BANK OF INDIA, NEAR PETROL PUMP MANDLA MANDLA, MADHYA PRADESH JABALPUR - 481661 India						DATE: 12.03.2024								
AMC PO NO :							SERVICE BRANC	H NAMI	E : BHOPAL					
SITE / ATM ID NO: N/A / S1BB000421004						SERVICE BRANCH CONTACT NO: 0755-2764201/2764202								
CONTACT PERSON NAME: MR.GANESH PRASAD						SERVICE BRANCH EMAIL ID : diwakar.yadav@numericups.com								
TELEPHONE/ MOBILE NO	: 7440	77732	27				SITE CATEGORY	: C						
Call Received on: 11.03.2024: 12:53:38						Call Registration No: 03879634								
Call Assigned on: 11.03.2024 : 13:17:56					Visit Attended on: 12.03.2024 : 12:02:50 Visit Completed on: 12				n: 12.0	2.03.2024 : 13:13:20				
Customer Category: Direct Sales					UPS TECHNOLOGY: DIGITAL HP		TYPE OF CALLS: Breakdown - 1PH UPS BD							
Customer Status: CAMC					UPS TYPE: 1P1		Call Type: Major							
					PRODUCT DETAILS - C	THERMA	KE/HP/2KVA/48V/1	-1/UNIT	ARY					
UPS KVA: 02			DC VO	LTS: 48	UPS SI.No: S1BB	SI.No : S1BB000421004 UPS CONFIG				ONFIGURATION : NA				
BATT AH : 100			BATT	VOLTS: 12V	BATT QTY: 16	TT QTY: 16 No OF SETS: N				NA				
BATT MAKE : EXIDE POW	ER SA	FE		BATT TYPE: VRLA			Batt Batch No : 4THO							
SERVO STABILIZER / ISO	LATION	N			KVA:			SI.No:	:					
			Р	RODUC	T DETAILS - Captured by site - engin	eer durin	g site visit - OTHEF	RMAKE	/HP/2KVA/4	8V/1-1/l	JNITARY			
UPS KVA: 02 DC V				DC VO	LTS: 48	UPS SI.No: S1BB000421004				UPS CONFIGURATION : NA				
BATT AH : 100			BATT VOLTS: 12V			BATT QTY: 16				No OF SETS : NA				
BATT MAKE: EXIDE POWER SAFE BAT				BATT	TYPE : VRLA	Batt Batch No: 4THO								
SERVO STABILIZER / ISOLATION					KVA:	SI.No:								
PROBLEM REPORTED BY	CUST	OMER	R: Backu	ıp Issue										
ROOT CAUSE OF FAILUR	E (ENG	INEE	RS OBS	ERVAT	ION): Spares Related									
FRONT PANEL INDICATION	N: NO	INDIC	CATION											
PROBLEM OBSERVED IN	WHICH	I MOE	DE: Worl	king On	Mains Mode									
ACTION TAKEN: SPARES	REPLA	ACE G	OOD C	ONDITIO	DN									
CONCLUSION OF FAILUR	E: Proc	duct R	elated B	ackup Is	sue									
Spare parts replaced, if an	ıy: (Mat	terial	code de	etails are	given in the front wrapper)									
ACTUAL SPARE PARTS FAILED DETAILS						ACTUAL SPARE PARTS REPLACED DETAILS								
SAP CODE				DE	ESCRIPTION QTY		SAP CODE			DESCRIPTION				QTY
SKDCHP3KPWR	SKD COMPONENT			PONEN ⁻	NT HP 3KVA PSDR BOARD 1.00		SKDCHP3KP\	WR SKD COM		MPONENT HP 3KVA PSDR BOARD			1.00	
UPS PARAMETERS					BATT PARAMERTERS	SITE PARAMETERS				GENERAL INFORMATION REG SITE				
PARAMETERS		R	Υ	В	DC Volts W/O Battery	109	Neutral to Earth Vo	oltage		1.6	Static bypass function	n test	No	
EB I/P Volts w.r.t Neutral		248			DC Volts with Battery	107	Power Failure Dura	ation / D	ay	1	Communication / Re	mote pannel	No	
EB I/P Current		2			DC Volts W/O Mains	98	No of time Power F	ailure /	Day	2	Tightness of all the t	ermination	Yes	
EB I/P Volts - Ph to Ph					Batt Charging Current	8	Input power variation	ariation 10 Appearance of the Battery		attery	WEAK CONDITION			
Bypass Voltage w.r.t Neutra	ıl .	248			Battery Condition - OK qty	6	Gen set availability	,		No	Input / Output break	status	OK	
UPS O/P Volts w.r.t Neutral		230			Battery Condition - weak qty	10	Dedicated Earth av	/ailability	/	Yes	Input / Output cable	status	OK	
UPS O/P Volts - Ph to Ph					Distilled water level	None	Room Temperature	9		26	Fan rotation		Yes	
UPS O/P Current		1.6			DC Low Cut off Volts	89	Air Conditioner/Ro	om Vent	tilation	No	General cleaning		Yes	
Type of Load ATM		ATM No of Parallel bank			1	Input frequency 50 Remarks : 10 NOS CONDITION.			Remarks : 10 NOS E CONDITION.	BATTERIES IN WE	AK			
UPS SYSTEM PRESENT S	TATUS	3 : Wo	rking Sa	tisfactor	ily		If PCB call-Appro	val stat	us : Open					

Numeric Engineer's Remarks / Suggestion : CHECK THE UPS AND BATTERIES FOUND UPS PSDR FAILURE CONDITION SO REPLACE THE SPARES GOOD CONDITION BUT CUSTOMER SITE 10 NOS BATTERIES IN WEAK CONDITION ADVICE TO CUSTOMER TO REPLACE ALL 16 NOS BATTERIES REPLACE TO PROPER BACKUP. UPS WORKING FINE.

The reported call has been completed and UPS is working satisfactorily on load, Preventive Maintenance carried out. EMP Code : NA

Customer Email id : tania.shekh@hitachi-payments.com

Customer signature: Signed By: GANESH PRASAD

Signed By: SUNIL KUMAR TIWARI Name & Designation : SUNIL KUMAR TIWARI & Technician

Payments can be made by the way of Demand Draff/RTGS and favouring NOVATEUR ELECTRICAL & DIGITAL SYSTEMS PRIVATE LIMITED. Cash mode of payment is not acceptable. For RTGS, Bank details are as follows - Bank A/C No. '0908810469600130, BNP PARIBAS , Chennai; RTGS / IFSC code:BNPA0009088.

NPDM/SER/FR/01/Rev 12

Signature :

	Back-up test										
			Individual	Individual Battery Voltages at regular interval while discharging							
S.NO.	.NO. BATTERY Batch No.	Health Check Status	SP.GR. ONLY TUBULAR BATT.	Battery volts during	I	II	III	IV	٧	VI	
				charger ON	10 minutes	20 minutes	30 minutes	40 minutes	50 minutes	60 minutes	
1	4THO	Good		13.07	12.15	12.10	12.06				
2	4THO	Weak		13.07	12.08	11.50	10.10				
3	4THO	Weak		13.07	12.04	11.20	10.10				
4	4THO	Good		13.07	12.20	12.12	12.08				
5	4THO	Good		13.07	12.22	12.14	12.18				
6	4THO	Weak		13.07	12.04	11.20	10.90				
7	4THO	Weak		13.07	12.09	11.90	10.80				
8	4THO	Weak		13.07	12.12	12.04	11.80				
9	4THO	Weak		13.07	12.18	12.11	11.90				
10	4THO	Good		13.07	12.14	12.08	12.04				
11	4THO	Weak		13.07	12.10	11.80	10.90				
12	4THO	Weak		13.07	12.11	12.01	11.90				
13	4THO	Good		13.07	12.22	12.14	12.06				
14	4THO	Weak		13.07	12.06	11.90	10.10				
15	4THO	Good		13.07	12.13	12.06	12.01				
16	4THO	Weak		13.07	12.09	11.80	10.10				
TOTAL	DTAL DC VOLTAGE				209.1						