SERVICE CALL REPORT - Exception Report Head Office: 10th Floor, Presige Centre Court, Office Block, Vijaya Forum Mall, 183, N.S.K Salai, Vadapalani, Chennai, Tamilnadu-600026 Customer Support Number - 0484 3103266 / 0484 4723266 : Support email id : customer.care@numericups.com CUSTOMER NAME & ADDRESS: SERVICE CALL REPORT NO: SA-4493114 STATE BANK OF INDIA, BHIKANGAON BRANCH NAGAR PANCHAYAT CAMPUS,NEAR BUS STAND, DISTRICT KHARGONE KHARGONE, MADHYA PRADESH **DATE:** 16.12.2024 BHIKANGAON - 451331 India AMC PO NO: SERVICE BRANCH NAME: BHOPAL SITE / ATM ID NO: N/A / NA SERVICE BRANCH CONTACT NO: 0755-2764201/2764202 SERVICE BRANCH EMAIL ID: purushottam.dwivedi-02@numericups.com CONTACT PERSON NAME : Mr. Mustafa Aarif TELEPHONE/ MOBILE NO: 9827617006 SITE CATEGORY: B Call Received on: 10.12.2024: 12:10:17 Call Registration No: 04602305 Call Assigned on: 10.12.2024 : 13:17:54 Visit Attended on: 16.12.2024 : 12:59:34 Visit Completed on: 16.12.2024 : 14:13:02 Customer Category: UPS TECHNOLOGY: DIGITAL HP TYPE OF CALLS: Breakdown - 1PH UPS BD UPS TYPE: 1P1 Customer Status: CAMC Call Type: Major PRODUCT DETAILS - HP/2KVA/96V/1-1/UNITARY UPS KVA: 02 DC VOLTS: 96 UPS SI.No: III044806345 UPS CONFIGURATION : NA **BATT AH:** 100 BATT VOLTS: 12V **BATT QTY:** 8 No OF SETS : NA BATT MAKE: AMARAJA QUANTA BATT TYPE: VRLA Batt Batch No: MOQ10047W SERVO STABILIZER / ISOLATION KVA: SI.No: PRODUCT DETAILS - Captured by site - engineer during site visit - HP/2KVA/96V/1-1/UNITARY UPS SI.No: III044806345 UPS CONFIGURATION: NA **UPS KVA: 02** DC VOLTS: 96

BATT QTY:8

Batt Batch No: MOQ10047W

SI.No:

No OF SETS : NA

PROBLEM REPORTED BY CUSTOMER: Ups Down

ROOT CAUSE OF FAILURE (ENGINEERS OBSERVATION): Spares Related

BATT VOLTS: 12V

BATT TYPE : VRLA

KVA:

FRONT PANEL INDICATION: NO INDICATION

BATT MAKE : AMARAJA QUANTA

SERVO STABILIZER / ISOLATION

BATT AH: 100

PROBLEM OBSERVED IN WHICH MODE: Working On Battery Mode

ACTION TAKEN: ups rectification has been done

CONCLUSION OF FAILURE: Customer Related Ups Down

Spare parts replaced, if any: (Material code details are given in the front wrapper)

ACTUAL SPARE PARTS FAILED DETAILS						ACTUAL SPARE PARTS REPLACED DETAILS				
SAP CODE	DESCRIPTION				QTY	SAP CODE		DESCRIPTION	QTY	
AIH03C01779	ASSEMBLED PCB HP CONTROL 1-3 KVA - 01779				1.00	AIH03C01779	9	ASSEMBLED PCB HP CONTROL 1-3 KVA - 01779	1.00	
SKDCHP3KPWR	SKD COMPONENT HP 3KVA PSDR BOARD				1.00	SKDCHP3KPWR		SKD COMPONENT HP 3KVA PSDR BOARD 1.0		
UPS PARAMETERS BATT PARAM				BATT PARAMERTERS		SITE PARAMETERS		GENERAL INFORMATION REG SITE		
PARAMETERS	R	Υ	В	DC Volts W/O Battery	109	Neutral to Earth Voltage	4	Static bypass function test	Yes	
EB I/P Volts w.r.t Neutral	250			DC Volts with Battery	109	Power Failure Duration / Day		Communication / Remote pannel	No	
EB I/P Current	5			DC Volts W/O Mains	100	No of time Power Failure / Day	2	Tightness of all the termination	Yes	
EB I/P Volts - Ph to Ph				Batt Charging Current	8	Input power variation	270	Appearance of the Battery	good	
Bypass Voltage w.r.t Neut	ral 250			Battery Condition - OK qty	8	Gen set availability	No	Input / Output break status	poor	
UPS O/P Volts w.r.t Neutr	al 230			Battery Condition - weak qty	0	Dedicated Earth availability		Input / Output cable status	poor	
UPS O/P Volts - Ph to Ph				Distilled water level		Room Temperature	29	Fan rotation	Yes	
UPS O/P Current	4			DC Low Cut off Volts	86.4	Air Conditioner/Room Ventilation	No	General cleaning	Yes	
Type of Load Atm+Network Equipment			No of Parallel bank	0	Input frequency	50	Remarks: UPS rectification has been done, mais and out put wiring and switch socket condition is very weak and poor need to replace and please remake the wiring properly, thease are cause of fire.			

UPS SYSTEM PRESENT STATUS: Working Satisfactorily

If PCB call-Approval status :



Numeric Engineer's Remarks / Suggestion : observation has been done. mains and out wiring and switch socket condition are not usable. nee to remake all wiring immediately. this is cause of fire. I have also advised last report.

The reported call has been completed and UPS is working satisfactorily on load, Preventive Maintenance carried out. EMP Code : NA

Customer Email id: sbi.30033@sbi.co

Customer signature: Signed By: Mr. Mustafa Aarif

Signed By: Balwant Singh Bisht Name & Designation : BALWANT SINGH BIST & Technician

Payments can be made by the way of Demand Draft/RTGS and favouring NOVATEUR ELECTRICAL & DIGITAL SYSTEMS PRIVATE LIMITED. Cash mode of payment is not acceptable. For RTGS, Bank details are as follows - Bank A/C No. '0908810469600130, BNP PARIBAS', Chennai; RTGS / IFSC code:BNPA0009088.

Signature: