SERVICE CALL REPORT - Exception Repor								port				NIIMFRIC°	
Head Office: 10th Floor, Presi	ge Centi	re Court,	Office B	Block, Vijaya Forum Mall, 183,	N.S.K Sala	i, Vadap	oalani, Chenn	nai, Tami	ilnadu-6	00026		HOME	VI C
HELP DESK TOLL FREE NO	<b>-</b> 1800 4	25 3266	: PH 04	4 4656 5555 : HO email id : he	elpdesk@ni	umericu	ps.com					A Group brand	egrand
	SS:						SERVICE	CALL R	EPORT	NO: SA-3	148204		
STATE BANK OF INDIA, HPCL PETROL PUMP,LALGHATI P.B.B BRANCH,KOH-E FIZA, MADHYA PRADESH BHOPAL India						DATE: 19.07.2023							
AMC PO NO :							SERVICE BRANCH NAME : BHOPAL						
SITE / ATM ID NO : N/A / S10	A014132	2015					SERVICE BRANCH CONTACT NO : 0755-2764201/2764202						
CONTACT PERSON NAME :	Sbi atm						SERVICE BRANCH EMAIL ID : diwakar.yadav@numericups.com						
TELEPHONE/ MOBILE NO : 6	3260454	697					SITE CATEGORY: B						
							Call Regis			259233			
				Visit Attended on: 19.07.2	2023 - 10-1	7:25	<del>'</del>				07.2023 : 11:40:26		
	20 . 10.1	1.03		UPS TECHNOLOGY: DIGIT		7.00					own - 1PH UPS BD		
				UPS TYPE: 1P1	IAL III				_		5WIT - 11 11 01 0 00		
Customer Status. CAIVIC					NICT DETA	uie ui	Call Type: Minor P/2KVA/96V/1-1/UNITARY						
					OCT DETA	AILS - III	UPS SI.No		IIANI	1			
UPS KVA: 02			DC VC	DLTS: 96			NL034122901 UPS CONFIGURATION : N.				A		
<b>BATT AH</b> : 65			BATT	VOLTS: 12V			BATT QTY	<b>Y</b> :8		No OF S	SETS : NA		
ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 425 32 ILEAD DESK TOLL FREE NO - 1800 14132015 ILEAD DESK TOLL FREE NO - 1800 14132015 ILEAD DESK TOLL FREE NO - 1800 14132015 ILEAD NO - 1800 150 14132015 ILEAD NO - 1800 14132015 ILEA			BATT TYPE: VRLA				Batt Batch No : 4TK03						
SERVO STABILIZER / ISOLA	TION		•	KVA:				SI.No :					
PRODUCT DETAILS - Captured by site - engineer during site visit - HP/2KVA/96V/1-1/UNITARY													
UPS KVA: 02			DC VC	<b>DLTS</b> : 96			UPS SI.No NL0341229			UPS CO	NFIGURATION : NA	A	
<b>BATT AH</b> : 65			BATT	VOLTS: 12V			BATT QTY	<b>Y</b> :8		No OF S	SETS : NA		
BATT MAKE : EXIDE POWER	R SAFE		BATT	TYPE : VRLA			Batt Batch	h <b>No</b> : 47	TK03				
SERVO STABILIZER / ISOLATION PROBLEM REPORTED BY CUSTOMER: Ups				KVA:	SI.No:								
PROBLEM REPORTED BY C	USTOM	ER: Ups	Trip										
								lue to 2 r	no batter	y weak co	ndition so ups trip no	ow rectified the issue and ups	working ok and
FRONT PANEL INDICATION:	BATT L	OW											
PROBLEM OBSERVED IN W	HICH M	ODE: Wo	orking O	n Mains Mode									
ACTION TAKEN: Ups working	fine wit	h load											
CONCLUSION OF FAILURE:	Battery	Related I	Ups Trip										
Spare parts replaced, if any:	(Materia	al code o	details a	re given in the front wrappe	r)		•						
Į.	ACTUAL	SPARE	PARTS	FAILED DETAILS						ACTUAL	SPARE PARTS RE	PLACED DETAILS	
SAP CODE			C	ESCRIPTION	QT	Y		SAP	CODE		DE	SCRIPTION	QTY
NA NA			NA	NA			NA				NA	NA	
UPS PARAM	ETERS			BATT PARAME	RTERS		SITE PA	ARAMET	TERS		GENERA	L INFORMATION REG SITE	
PARAMETERS	R	Υ	В	DC Volts W/O Battery		108	Neutral to I Voltage	Earth	1	Static by	pass function test		No
EB I/P Volts w.r.t Neutral	237			DC Volts with Battery		109	Power Fail Duration / I		1	Commun	nication / Remote pa	nnel	No
EB I/P Current	3			DC Volts W/O Mains		100	No of time Failure / Da		1	Tightnes	s of all the termination	on	Yes
EB I/P Volts - Ph to Ph				Batt Charging Current		2	Input power variation	er	250	Appeara	nce of the Battery		2 no battery weak condition
Bypass Voltage w.r.t Neutral				Battery Condition - OK qty		6	Gen set availability  Dedicated		No		output break status		Good
UPS O/P Volts w.r.t Neutral	230			Battery Condition - weak	qty	2	availability		Yes		output cable status		Good
UPS O/P Volts - Ph to Ph				Distilled water level		None	Temperatu	ıre	30	Fan rota	tion		Yes
UPS O/P Current	1			DC Low Cut off Volts		87	Conditione Ventilation		No	General cleaning			Yes
Type of Load Atm+Network Equipment No of I				lo of Parallel bank		0	Input frequ	ut frequency 50 2 no battery wea working ok and a		tery weak condition so ok and advice to cus	and found 30 minutes battery backup checking due to ndition so ups trip now rectified the issue and ups e to customer replace to all 8no battery immediately over more than 4 years old		
UPS SYSTEM PRESENT STA	TUS : V	Vorking S	Satisfacto	orily			If PCB cal	I-Appro	val statı	us : Open			
Numeric Engineer's Remarks / Suggestion :  Signature :  Signed By: RAKESH MEHAR Name & Designation : RAKESH MEHAR & Technician				The reported call has been completed and UPS is working satisfactorily on load, Preventive Maintenance carried out.  EMP Code:.  Customer Email id: priyam.srivastav@hitachi-payments.com									
Signed By: RAKESH MEHAR Name & Designation: RAKESH MEHAR & Technician					Customer signature: Signed By: shailendra								

Payments can be made by the way of Demand Draft/RTGS and favouring NOVATEUR ELECTRICAL & DIGITAL SYSTEMS PRIVATE LIMITED. Cash mode of payment is not acceptable. For RTGS, Bank details are as follows - Bank A/C No. '0908810469600130, BNP PARIBAS', Chennai; RTGS / IFSC code:BNPA0009088.

NPDM/SER/FR/01/Rev 12

Back-up test											
	S.NO. BATTERY Batch No.		SP.GR. ONLY TUBULAR BATT.	Individual	Individual Battery Voltages at regular interval while discharging						
S.NO.		Health Check Status		Battery volts during	I	II	III	IV	٧	VI	
			charger ON	10 minutes	20 minutes	30 minutes	40 minutes	50 minutes	60 minutes		
1	4TK03	Good		13.06	12.36		12.06				
2	4TK03	Weak		13.06	12.40		10.30				
3	4TK03	Good		13.06	12.42		12.06				
4	4TK03	Good		13.06	12.45		12.36				
5	4TK03	Good		13.06	12.60		12.26				
6	4TK03	Good		13.06	12.51		12.40				
7	4TK03	Good		13.06	12.06		12.36				
8	4TK03	Weak		13.06	12.36		11.01				
TOTAL	OTAL DC VOLTAGE										