## SERVICE CALL REPORT - Exception Report Head Office: 10th Floor, Presige Centre Court, Office Block, Vijaya Forum Mall, 183, N.S.K Salai, Vadapalani, Chennai, Tamilnadu-600026 Customer Support Number - 0484 3103266 / 0484 4723266 : Support email id : customer.care@numericups.com CUSTOMER NAME & ADDRESS: SERVICE CALL REPORT NO: SA-4030698 STATE BANK OF INDIA, ATM, SPGC OIL CORPORATION COLLECTORATE VIRUDHUNAGAR, TAMIL NADU DATE: 19.06.2024 VIRUDHUNAGAR - 626001 AMC PO NO: SERVICE BRANCH NAME: MADURAI SITE / ATM ID NO: / S1BW000951005 SERVICE BRANCH CONTACT NO: 0452-2604555/2602629 CONTACT PERSON NAME: CUSTODIAN SERVICE BRANCH EMAIL ID: jebarsingh.aruldhas@numericups.com TELEPHONE/ MOBILE NO: 6382880269 SITE CATEGORY : B Call Received on: 18.06.2024: 21:34:44 Call Registration No: 04143860 Call Assigned on: 19.06.2024: 13:12:39 Visit Attended on: 19.06.2024: 20:18:31 Visit Completed on: 19.06.2024 : 21:06:00 Customer Category: Direct Sales UPS TECHNOLOGY: DIGITAL HP TYPE OF CALLS: Breakdown - 1PH UPS BD Customer Status: CAMC UPS TYPE: 1P1 Call Type: Major PRODUCT DETAILS - U4DHP/3KVA/FMI/96V/UNI/SNMP/DISPLAY-L DC VOLTS: 96 UPS SI.No: III051702194 UPS KVA: 03 **UPS CONFIGURATION: UNI** BATT VOLTS: 12V **BATT AH: 100 BATT QTY:** 8 No OF SETS : NA BATT MAKE: EXIDE POWER SAFE BATT TYPE : VRLA Batt Batch No: 4PJ SERVO STABILIZER / ISOLATION SI.No PRODUCT DETAILS - Captured by site - engineer during site visit - U4DHP/3KVA/FMI/96V/UNI/SNMP/DISPLAY-L **UPS KVA: 03** DC VOLTS: 96 UPS SI.No: III051702194 **UPS CONFIGURATION: UNI BATT AH**: 100 BATT VOLTS: 12V BATT QTY: 8 No OF SETS : NA BATT TYPE : VRLA **BATT MAKE: EXIDE POWER SAFE** Batt Batch No: 4PJ SERVO STABILIZER / ISOLATION SI.No PROBLEM REPORTED BY CUSTOMER: Ups Down ROOT CAUSE OF FAILURE (ENGINEERS OBSERVATION): Battery Related FRONT PANEL INDICATION: BATT LOW PROBLEM OBSERVED IN WHICH MODE: Change Over From Mains To Battery ACTION TAKEN: UPS IS OK, BATTERY WEAK CONDITION CONCLUSION OF FAILURE: Product Related Ups Down Spare parts replaced, if any: (Material code details are given in the front wrapper) ACTUAL SPARE PARTS FAILED DETAILS ACTUAL SPARE PARTS REPLACED DETAILS SAP CODE DESCRIPTION OTY SAP CODE DESCRIPTION ΩТΥ NA NΑ **UPS PARAMETERS** BATT PARAMERTERS SITE PARAMETERS **GENERAL INFORMATION REG SITE** Neutral to Earth PARAMETERS R Υ В DC Volts W/O Battery 108 Static bypass function test Yes Voltage Power Failure EB I/P Volts w.r.t Neutral 228 DC Volts with Battery 108 Communication / Remote pannel No Duration / Day No of time Power EB I/P Current 2 DC Volts W/O Mains 100 Tightness of all the termination Yes Input power EB I/P Volts - Ph to Ph GOOD **Batt Charging Current** 4.2 248 Appearance of the Battery variation Gen set availability ΟK Bypass Voltage w.r.t Neutral 228 Battery Condition - OK qty No Input / Output break status Dedicated Earth UPS O/P Volts w.r.t Neutral 230 Battery Condition - weak qty Yes Input / Output cable status OK UPS O/P Volts - Ph to Ph Distilled water level None Fan rotation Yes UPS O/P Current 2 DC Low Cut off Volts 87 Conditioner/Roor Ventilation Remarks : FOUND BATTERY LIFE EXPIRED AND WEAK CONDITION SO WE SUGGEST TO THE CUSTOMER GO FOR NEW BATTERY FOR Atm+Network BATTER BACKUP, AC NOT WORKING SO PROPER VENTILATION IS No of Parallel bank Type of Load Input frequency REQUIRED, UPS COVERED BY UNWANTED METERIALS WITH DUST, Equipment SO CUSTOMER SHOULD PROVIDE SUFFICIENT SPACE FOR UPS UPS SYSTEM PRESENT STATUS : RWF If PCB call-Approval status : Open Numeric Engineer's Remarks / Suggestion Customer Email id : sangavi.s@hitachi-payments.com Signature: Signed By: G ARUMUGARAJ Name & Designation : ARUMUGARAJ GANESAN & Technician Signed By: CUSTODIAN

Payments can be made by the way of Demand Draft/RTGS and favouring NOVATEUR ELECTRICAL & DIGITAL SYSTEMS PRIVATE LIMITED. Cash mode of payment is not acceptable. For RTGS, Bank details are as follows - Bank A/C No. '0908810469600130, BNP PARIBAS, Chennai; RTGS / IFSC code:BNPA0009088.