



CASH & DIGITAL PAYMENT SOLUTIONS

INCIDENT REPORT

Hitachi Payment Services Pvt. Ltd.

Incident detail



| Incident Details |
|---|
| Date: 26 th Feb. 2023 |
| Time: 20:04:37. |
| Bank: PNB. |
| Site ID: N3289100. |
| Address: CHAKRATIRTHA ROAD, PNB GT ROAD, NEW STATION ROAD |
| City: Bhubaneswar |
| State: Orissa |
| |
| Incident Type |
| Status: Vandalism (Shutter Assembly). |
| Loss if Any: - |

Investigation Report:-



| Alerts Details | 28-02-2023 11:47:- We received information that the shutter tempering happen at site. |
|-----------------------------------|--|
| | Transaction happened in time limit and there are no sensor's on the shutter to deter tampering of the ATM. |
| | |
| Monitoring Team- Activity Details | 28-02-2023 11:47:- After getting information on shutter tempering, team checked the footage. |
| | Based on the footage, the team has shared information. |

Chronology of Incident



Playback Observation:

| Sr. No | Date | Time | Description |
|--------|------------|----------|--|
| 1 | 26-02-2023 | 20:04:28 | Culprits enter the premises. (Where the second culprit was standing behind the first culprit, and two other culprits were standing outside the premises) |
| 2 | 26-02-2023 | 20:04:37 | With the help of screwdriver the culprit has damage the cash dispenser. |
| 3 | 26-02-2023 | 20:04:56 | Then he inserted some equipment into the cash dispenser. |
| 4 | 26-02-2023 | 20:05:09 | After that they culprit left the premises. |
| 5 | 26-02-2023 | 20:28:54 | Again Culprit enter the premises and pretend to do transaction. |
| 6 | 26-02-2023 | 20:29:21 | Then the culprit removes the equipment and cash from cash dispenser. |
| 7 | 26-02-2023 | 20:30:37 | After that, they left the premises. |

Chronology of Incident



Transaction Details:

| Sr. No | Date | Time | Description |
|--------|------------|----------|---|
| 1 | 26-02-2023 | 20:15:49 | Customers attempted to make the transaction but were unable to do, so he left the premises. |
| 2 | 26-02-2023 | - | After that customer are unable to do the transaction, so they left the premises. |

Root Cause Analysis:

After getting such information about the incident, we have checked the playback.

Incident – Snapshots:-















Incident – Snapshots:-









Customer Cash Stuck Snapshots:







CASH & DIGITAL PAYMENT SOLUTIONS

Thank You

Hitachi Payment Services Pvt. Ltd.