
Account Name: TSI_FS

LOG OUT



87



| House Keeping Issue:* | No Issue Look & Feel | |
|----------------------------------|-------------------------------------|--|
| House Keeping Issue | 0 | |
| - Cost:* | | |
| House Keeping Comment: | | |
| UPS Issue:* | No Issue UPS not getting ON | |
| UPS Issue - Cost:* | 0 | |
| UPS Comment: | | |
| AC Issue:* | No Issue Noising | |
| AC Issue - Cost:* | 0 | |
| AC Comment: | | |
| Miscellaneous :* | No Issue Access Lock ▼ | |
| Miscellaneous - Cost:* | 0 | |
| Miscellaneous Comment: | | |
| Special Activities:* | No Issues Site Dismantling | |
| Special Activities - Cost:* | 0 | |
| Special Activities Comment: | | |
| E-surveillance: | No Issue E-surveillance Dismantling | |
| E-surveillance Cost: | 0 | |
| E-surveillance Comment: | | |
| Grand Total of all ① Cost:* | 1400 | |
| Cost Type:* | Rate Card 🗸 | |
| Commercial Approval Request:* | LT - Rs 5000 ✓ | |
| ETA Date:* | | |
| CE Comment: | | |
| Approved Amount:* | 1400 | |

| RCM Approval on Cost: | Approved 🗸 | | |
|-----------------------------------|---|-----------------------------|----------------------------|
| | Approved for mini IT installation for res | solving high earthing issue | |
| | 71 | | |
| | | | |
| SAL Approval:* | Approved | | |
| SAL Comment: | Ok | | |
| | | | |
| Business Finance | Approved ✓ | | // |
| Head Approval:* | | | |
| Business Finance Head Approval | 25/07/2024 | | |
| Date:* | | | |
| BF Comment: | Ok | | |
| | | | |
| Desference | | | |
| Performance Analysis: | | | |
| Corporate CM | Y | | |
| Approval:* | | | |
| Vendor Status: | ~ | 1 | |
| Vendor Remarks: | | | |
| Completion Status:* | Not Started 🗸 | | |
| Work Completion Date:* | 18/07/2024 | | |
| Ageing on Work | N/A | | |
| Completion: | | | |
| Ageing on Issue Completion: | N/A | | |
| Billing Info: | | | |
| Invoice submission: | V | | |
| Invoice submission | | | |
| date: | | | |
| Invoice Billed vendor: | Y | - | |
| Invoice number:* | | | |
| Invoice Status: | ~ | [| |
| | | English | ✓ Check Spelling |
| Status:* | Approved by BF ✓ | Assigned to: | CSS ✓ □ 🕍 |
| Severity: | V | Reported by: | Odisha_FS • • |
| , | | CC: | |
| | | | Abhishek.Kumar ac.vendor • |
| | | | |
| Submitted on: | 10/07/2024 | | |
| Remarks: | | | |
| | | | |
| | | | // |
| Linked Records: | TSI_FS 🔻 | ☐ COPY: | Issue Tracking 🔻 |
| Attach: | | | |



* - required fields





Attached Files: Check to delete attached file(s)



RE Earthing issue. ATM ID-FFBR000016024Site-SBIO200078 AT-BATESWARPO-MOTIGANJA GOLA POKHARIBALASORE.msg

17/07/2024 1:03:38 PM;



RE Ext RE Earthing issue. ATM ID-FFBR000016024Site-SBIO200078 AT-BATESWARPO-MOTIGANJA GOLA POKHARIBALASORE.msg

18/07/2024 2:49:59 PM;



| Author | Message | | |
|-------------------------------------|--|--|--|
| Odisha_FS 10/07/2024 12:00:33 PM | Captioned site is having high Earthing issue. Please align an electrician to fix this at the earliest. | | |

History Trail

| Date | Time | User Name | Field Name | Change |
|------------|-------------|-------------------|--|---|
| 25/07/2024 | 05:25:08 PM | TSI_ATM_O_CG | Assigned to | TSI_ATM_O_CG => CSS |
| | | | BF Comment | Content change |
| | | | Business Finance Head Approval | NULL => Approved |
| | | | Business Finance Head Approval Date | NULL => 25/07/2024 |
| | | | Status | Approved by SAL => Approved by BF |
| 25/07/2024 | 04:46:08 PM | Clusterhead.OR.CH | Assigned to | Clusterhead.OR.CH => TSI_ATM_O_CG |
| | | | SAL Approval | NULL => Approved |
| | | | SAL Comment | Content change |
| | | | Status | RCM Approval Required => Approved by SAL |
| 24/07/2024 | 12:53:56 PM | Orissa.RM | Approved Amount | NULL => 1400 |
| | | | Assigned to | Orissa.RM => Clusterhead.OR.CH |
| | | | Email notification has been sent to: | Reported by: Odisha_FS |
| | | | RCM Approval on Cost | NULL => Approved |
| | | | RCM Comment | Content change |
| 18/07/2024 | 02:49:59 PM | CSS | Attachment | File attached: RE Ext RE Earthing issue. ATM ID-FFBR000016024Site-SB IO200078 AT-BATESWARPO-MOTIGANJA GOLA POKHARIBALASORE. msg |
| | | | Electrical Comment | CSS/TSIPL/189/Jul/2024-25 Sr issue (a) earthing deviseMini I.T 1000 1 1000 (b) HUNDRED ONLY) 1400 For Clear Secured Services Pvt Ltd |
| 17/07/2024 | 01:03:38 PM | CSS | Assigned to | CSS => Orissa.RM |
| | | | Attachment | File attached: RE Earthing issue. ATM ID-FFBR000016024Site-SBIO2000 78 AT-BATESWARPO-MOTIGANJA GOLA POKHARIBALASORE.msg |
| | | | Commercial Approval Request | NULL => LT - Rs 5000 |

| * | | | | - |
|------------|-------------|-----------|--------------------------------------|--|
| | | | Cost Type | NULL => Rate Card |
| | | | Electrical Comment | Content change |
| | | | Electrical Issue | No Issue => Normal Earthing |
| | | | Electrical Issue - Cost | 0 => 1400 |
| | | | Grand Total of all Cost | 0 => 1400 |
| | | | Status | Indent Raised => RCM Approval Required |
| | | | Visit Date | NULL => 17/07/2024 |
| | | | Work Completion Date | NULL => 18/07/2024 |
| 10/07/2024 | 12:00:33 PM | Odisha_FS | Email notification has been sent to: | Assigned to: CSS Reported by: Odisha_FS |
| | | | New issue submitted | |

 $\ @$ 2000-2024, Elementool INC. All Rights Reserved.

<u>Contact Us</u> <u>Privacy Policy</u> <u>Legal</u>