



BEAM ANNOTATION AUTOMATION





Assign Tags to all Structural Framing that contains "Mark" parameter












Correction is applied to horizontal and vertical beams if numbering is not as per expectations




Since, the script number the beams on basis on starting coordinate, the output numbering did not come as per requirement.



Correction applied to horizontal beams





Same method is applied to vertical beams with scripts "Beam3_ CORRECTION DONE TO VERTICAL BEAMS" scripts