

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

40 Mount Taylor road

Field Manager

Andrew McKinnon

CSA

07

iTools Reference number -

138750

Conducted on

14 May 2018 02:33 AM

Prepared by

Kranthi Kumar Thota

Score

16/27.0 - 59.26%

Audit - 10/20 50.00%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft, Surface Mount	
Excavation type	Trench - linear meters	
How many meters?	16.5 metres	
Hard surface type	Concrete	
Excavation type	Concrete Slot Cut - Linear Meters	
How many meters?	3 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	nA	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 6/7 85.71%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	

2) Photos of MDU/ROW starting point as per scoping document.



Appendix 1

Additional information of MDU/ROW starting point as per scoping document	
Photo of surfaces prior to works e.g trenching / slot cutting	Yes

Photo of surfaces prior to works e.g trenching / slot cutting







Appendix 2

Appendix 3

Appendix 4

Additional information of surfaces prior to works e.g trenching / slot cutting	
Photos where change in methodology occurs e.g. shallow trench to surface mount	No - N/A
Why no photo's where methodology changes?	There is no changes in methodology
Photos where change in surface type occurs	Yes

Question **Details** Response Photos where change in surface type occurs Appendix 5 Appendix 6 Appendix 7 Additional information where change in surface type occurs Photos where assets installed e.g. hand Yes holes, IFDB's, Pedestals, BUD's, boundary Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs Appendix 8 Appendix 9 Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs Photos of surfaces after final permanent Yes reinstatment Photos of surfaces after final permanent reinstatment Appendix 10 Appendix 11 Appendix 12 Appendix 13 Additional information - e.g dimensions NA of concrete cut, removed and reisntated.

Yes

Is site ready for provisioning?

Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12



Appendix 13