

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

2/48 Sackville street, Grey Lynn, Auckland

Field Manager

Neil panther

CSA

07

iTools Reference number -

132526

Conducted on

05 Apr 2018 02:48 AM

Prepared by

Kranthi Kumar Thota

Completed on

05 Apr 2018 05:28 AM

Score

14/25.0 - 56.00%

Audit - 8/18 44.44%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Surface Mount	
Hard surface type	Concrete	
Excavation type	Concrete Slot Cut - Linear Meters	
How many meters?	22.5 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	0	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 6/7 85.71%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	

2) Photos of MDU/ROW starting point as per scoping document.



Appendix 1

Additional information of MDU/ROW starting point as per scoping document	Install handhole, left ruggedize from FAT
Photo of surfaces prior to works e.g trenching / slot cutting	Yes

Photo of surfaces prior to works e.g trenching / slot cutting



Appendix 2

Additional information of surfaces prior to works e.g trenching / slot cutting	
Photos where change in methodology occurs e.g. shallow trench to surface mount	No - N/A
Why no photo's where methodology changes?	No need to change methodology, we worked according to plan
Photos where change in surface type occurs	Yes

Question **Details** Response Photos where change in surface type occurs Appendix 3 Appendix 4 Additional information where change in surface type occurs Photos where assets installed e.g. hand Yes holes, IFDB's, Pedestals, BUD's, boundary Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs Appendix 6 Appendix 5 Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs Photos of surfaces after final permanent Yes reinstatment Photos of surfaces after final permanent reinstatment Appendix 7 Appendix 8 Appendix 9

N/A

Yes

Additional information - e.g dimensions

Is site ready for provisioning?

of concrete cut, removed and reisntated.

Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9