UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

1D ALANBROOKE CRESCENT, Avondale

Field Manager

Neil panther

CSA

07

iTools Reference number -

132307

Conducted on

26/02/2561 BE, 10:23 AM

Prepared by

Kranthi Kumar Thota

Score

17/27 - 62.96%

Audit - 10/20 - 50%

Question	Response	Details	
Site Type	ROW - Right of Way		
Class key	Class 1 - MDU/ROW 2-5		
Fibre Installation Checklist - Communal Area	Hard, Soft, Surface Mount		
Excavation type	Trench - linear meters		
How many meters?	3.9 metres		
Hard surface type	Concrete		
Excavation type	Concrete Slot Cut - Linear Meters		
How many meters?	9.4metres		
Hardware Installation Checklist	Other		
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	2metres conduit		
Was the equipment installed, laid up and labelled correctly?	Yes		
Has CVLS testing been completed?	N/A ABF		

As-built photo evidence - 7/7 - 100%

Question		Response		Details	
Photo of MDU/ROW starting poir design document	nt as per	Yes			
2) Photos of MDU/ROW starting point as per scoping document.					
Appendix 1					
Additional information of MDU/Restarting point as per scoping doc					
Photo of surfaces prior to works trenching / slot cutting	e.g	Yes			
Photo of surfaces prior to works e.g trenching / slot cutting					
Appendix 2 Appendix 3	Append	lix 4 App	New 26th 10ck SECT	Appendix 6	
Additional information of surface works e.g trenching / slot cutting	-				
Photos where change in methodo occurs e.g. shallow trench to sur		Yes			
Photos where change in methodology occurs e.g. shallow trench to surface mount					
Suit standard and Suit Suit Suit Suit Suit Suit Suit Suit	5.0050000000000	doncista (

surface mount

methodology occurs e.g. shallow trench to

Quest	tion	Response	Details	
Photos where change in type occurs	n surface	Yes		
Photos where change in surface type occurs				
Ruta A has bit a concert Supplementation 1.0 Appropriation 1.0 Appropriation 1.0 Appropriation 1.0 Appropriation 1.0				

Appendix 10

Appendix 11

Appendix 12

Additional information where change in
surface type occurs

Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs

Yes

Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs





Appendix 13

Appendix 14

Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs

Photos of surfaces after final permanent reinstatment

Yes

Photos of surfaces after final permanent reinstatment









Appendix 15

Appendix 16

Appendix 17

Appendix 18

Additional information - e.g dimensions of concrete cut, removed and reisntated.

Question	Response	Details
Is site ready for provisioning?	Yes	

Media



Appendix 1



Appendix 3



Appendix 2



Appendix 4




Appendix 5



Appendix 7



Appendix 6



Appendix 8




Appendix 9



Appendix 11



Appendix 10



Appendix 12



Appendix 13



Appendix 15



Appendix 14



Appendix 16





Appendix 17

Appendix 18