

Inventory Item	Description
SUPPLY_TYPE	Blown fibre
DEPLOY_LEADIN_TOPOLOGY	Error: No Lead-in route found.
DEPLOY_LEADIN_CABLE_STATUS	Fibre not installed
DEPLOY_LEADIN_MICRODUCT_ID	F-AMI325 12
DEPLOY_LEADIN_LEADIN_DISTANCE	116.0 m
DEPLOY_LEADIN_LEADIN_DISTAN...	Error: Lead-in distance not available.
DEPLOY_LEADIN_SERVING_ENCL...	Installed Asset
DEPLOY_LEADIN_SERVING_ENCL...	ABFFP AB
DEPLOY_LEADIN_SERVING_ENCL...	F-AMI325
DEPLOY_LEADIN_SERVING_ENCL...	8 NORDON PLACE, Remuera, Auckland
GPON_SPLITTER_ENCLOSURE_TY...	ABFFP
GPON_SPLITTER_PATCH_FFP	F-AMI325
GPON_SPLITTER_PATCH_FFP_LOC...	8 NORDON PLACE, Remuera, Auckland