

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

78 Magma Crescent

Field Manager

Neil panther

CSA

07

iTools Reference number -

137184

Conducted on

19 Apr 2018 10:51 PM

Prepared by

Kranthi Kumar Thota

Completed on

22 Apr 2018 10:37 PM

Score

16/27.0 - 59.26%

Audit - 10/20 50.00%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft, Sเ	ırface Mount
Excavation type	Trench - linea	ar meters
How many meters?	12.3 metres	
Hard surface type	Concrete	
Excavation type	Concrete Slot	: Cut - Linear Meters
How many meters?	7 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	1*21metres(2 1* T-joint 2*25mm ben	•
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 6/7 85.71%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	

2) Photos of MDU/ROW starting point as per scoping document.



Appendix 1

Additional information of MDU/ROW starting point as per scoping document	
Photo of surfaces prior to works e.g trenching / slot cutting	Yes

Photo of surfaces prior to works e.g trenching / slot cutting













Appendix 2

Appendix 3

Appendix 4

Appendix 5

Appendix 6

Appendix 7

Additional information of surfaces prior to works e.g trenching / slot cutting		
Photos where change in methodology occurs e.g. shallow trench to surface mount	No - N/A	
Why no photo's where methodology changes?	There is no needed to change in methodology	

Question	Response	Details
Photos where change in surface type occurs	Yes	
Photos where change in surface type occur	'S	
Appendix 8 Appendix 9 Appendix 10 Appendix 11 Appendix 12		
Additional information where change in surface type occurs		
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs	Yes	
Photos where assets installed e.g. hand ho	les, IFDB's, Ped	estals, BUD's, boundary pegs
Appendix 13 Appendix 14		
Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		

Yes

Photos of surfaces after final permanent

reinstatment

Question Response Details

Photos of surfaces after final permanent reinstatment













Appendix 15

Appendix 16

Appendix 17

Appendix 18

Appendix 19

Appendix 20

Additional information - e.g dimensions of concrete cut, removed and reisntated.	NA
Is site ready for provisioning?	Yes

Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12



Appendix 13



Appendix 14



Appendix 15



Appendix 16



Appendix 17



Appendix 18



Appendix 19



Appendix 20