

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

69 Marine Parade

Field Manager

Neil panther

CSA

07

iTools Reference number -

133054

Conducted on

3/03/2561 BE, 9:40 AM

Prepared by

Kranthi Kumar Thota

Score

19/27 - 70.37%

Audit - 12/20 - 60%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft, Surface Mount, Jointing, Hauling	
Excavation type	Trench - linear meters	
How many meters?	0.5 metres	
Hard surface type	Concrete	
Excavation type		
How many meters?	11.7 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	0.5 metres conduit	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 7/7 - 100%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	
2) Photos of MDLI/ROW starting point as per scoping document		

os of MDU/ROW starting point as per scoping document.



Appendix 1

Additional information of MDU/ROW starting point as per scoping document	
Photo of surfaces prior to works e.g trenching / slot cutting	Yes

Photo of surfaces prior to works e.g trenching / slot cutting



Appendix 2



Appendix 3



Appendix 4

Additional information of surfaces prior to works e.g trenching / slot cutting	
Photos where change in methodology occurs e.g. shallow trench to surface mount	Yes

Photos where change in methodology occurs e.g. shallow trench to surface mount



Appendix 5



Appendix 6

Additional information where change in methodology occurs e.g. shallow trench to surface mount

Question	Response	Details
Photos where change in surface type occurs	Yes	

Photos where change in surface type occurs





Appendix 7

Appendix 8

Additional information where change in surface type occurs	
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs	Yes

Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs





Appendix 9

Appendix 10

Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs	
Photos of surfaces after final permanent reinstatment	Yes

Photos of surfaces after final permanent reinstatment







Appendix 11

Appendix 12

Appendix 13

Additional information - e.g dimensions of concrete cut, removed and reisntated.

Question	Response	Details
Is site ready for provisioning?	Yes	

Media



Appendix 1



Appendix 3



Appendix 2



Appendix 4



Appendix 5



Appendix 7



Appendix 6



Appendix 8



Appendix 9



Appendix 11



Appendix 10



Appendix 12



Appendix 13