



LASER SOURCE TECHNICAL ASSESSMENT REPORT

BASIC DETAILS		CUSTOMER DETAILS	
TAR NO:	TAR-2026-0010	COMPANY NAME:	Zuesskill Forge foundation
START DATE:	2026-07-01		
END DATE:	2026-07-03	CONTACT PERSON:	Zuesskill Forge foundation
DEPARTMENT:	SERVICE & REPAIR	CONTACT NUMBER:	+918210708134
SOURCE DETAILS		REPORTED BY	
MAKE:	Raycus	NAME:	Manikandan
ML.NO:		EMPLOYEE ID:	c99ab35f
SL.NO:	dfdf	☒ TEAM A	☐ TEAM B
MFG DATE:	2026	☒ IN-HOUSE REPAIR	☐ ONSITE
MODULE DETAILS:	☒ SINGLE-MODULE ☐ MULTI-MODULE ☐ UAE		
CUSTOMER REPORTED PROBLEM: dfdf			
TYPES OF PROBLEMS			
☒ QBH/LOE/QD+/Q+ CABLE SPOT ☐ LOW POWER ☐ COMBINER PROBLEM ☐ ACTIVE FIBER PROBLEM ☐ PSU/CONTROL BOARD ISSUE ☐ OTHERS			
PRE-REPAIR INSPECTION			
EQUIPMENT/SOURCE CONDITION:		PREVIOUS REPAIR DETAILS:	
☐ GOOD ☐ FAIR ☐ POOR		☒ AVAILABLE ☐ NA	
☐ UNDER WARRANTY ☒ NO WARRANTY			
☒ CUSTOMER ☐ DEALER ☐ STANDBY ☐ FREELANCER			
INITIAL OBSERVATION BY REPAIR ENGINEERS			
SOURCE PACKAGE CONDITION	☒ OK	☐ NOT OK	
QBH CONDITION	☒ OK	☐ NOT OK	
EXTERNAL DAMAGE	☒ YES	☐ NO	
INTERNAL DAMAGE	☒ YES	☐ NO	
POWER CABLE	☒ YES	☐ NO	
INTERFACE CABLE	☒ YES	☐ NO	
SOURCE KEY	☒ YES	☐ NO	
OTHERS: Checked Obs: SOURCE KEY is NO			
FUNCTIONAL TEST POINT			
EMERGENCY SWITCH	☐ OK ☒ NOT OK	LASER BUTTON ON KEY	☒ OK ☐ NOT OK
SOURCE START KEY	☒ OK ☐ NOT OK	MAIN MCB	☒ OK ☐ NOT OK
PROBLEM IN	☒ OPTICAL SECTION ☐ ELECTRICAL SECTION		
INITIAL OBSERVATION REPORTED BY: gkj			
IMMEDIATE ACTION TAKEN: hjgkh			
REQUIRED SPARE PARTS/ TOOLS: mhvh			
ESTIMATED DOWN TIME: 1-2 Daysjh			

FINAL TEST REPORT						
REDLIGHT VISIBILITY		☐ GOOD		☒ FAIR		☐ POOR
	0%	25%	50%	75%	100%	
LASER OUTPUT POWER	0	25%	50%	75%	100%	
POWER METER READING	0W	750W	1500W	2250W	3000W	
PUMP AMPS DETAIL	0 A	2.5 A	5 A	7.5 A	10 A	
CHECKLIST		OBSERVED VALUE		MAX VALUE		STATUS
OPTICAL SECTION TEMP	24	32°C	☒ GOOD	☐ FAIR	☐ POOR	
ELECTRICAL SECTION TEMP	25	32°C	☒ GOOD	☐ FAIR	☐ POOR	
LASER PUMP TEMP	26	40°C	☒ GOOD	☐ FAIR	☐ POOR	
HUMIDITY (OPTICAL SEC)	35	50%	☒ GOOD	☐ FAIR	☐ POOR	
HUMIDITY (ELECTRICAL SEC)	36	50%	☒ GOOD	☐ FAIR	☐ POOR	
WATER FLOW IN QBH	1.2	1.4Lpm	☒ GOOD	☐ FAIR	☐ POOR	
WATER FLOW IN SOURCE	4.0	4.2Lpm	☒ GOOD	☐ FAIR	☐ POOR	
TEMP IN SPLICING POINT	298	320K	☒ GOOD	☐ FAIR	☐ POOR	
TEMP IN QBH CONNECTOR	295	300K	☒ GOOD	☐ FAIR	☐ POOR	
PROBLEM ANALYSIS: CXCX						
ROOT CAUSE ANALYSIS: gfg						
FAILURE TYPE						
☐ HUMAN ERROR ☐ ELECTRICAL ERROR ☒ ENVIRONMENTAL ISSUE ☐ EXTERNAL PROBLEM			☒ MECHANICAL ERROR ☒ SOFTWARE ISSUE ☐ SPARE LIFETIME EXPIRY			
REPAIR AND TESTING						
REPAIR ACTION TAKEN		☒ YES	☐ NO	PARTS REPLACED		☒ YES ☐ NO
POST REPAIR TESTING RESULT		☒ PASS	☐ FAIL	TRAIL RUNNING DURATION yty		
FINAL VERIFICATION						
EQUIPMENT RUNNING CONDITION		☒ OK		☐ NOT OK		
VERIFIED BY: Manikandan		APPROVED BY: Service Manager			CUSTOMER SIGN:	
REMARK: demo						
PAYMENT DETAILS						
☒ INVOICE		☐ NON-INVOICE		INVOICE NO: vfhgkj		
DISPATCH DETAILS:		☒ TRANSPORT/COURIER		☐ CUSTOMER VEHICLE		☐ PORTER