



LASER EXPERTS INDIA LLP

27/3 ANUMEPALLI
BEGAPALLI ROAD , ZUZUVADI
HOSUR 635126
TAMIL NADU 33
PAN NO AAGFL9943F
GSTIN 33AAGFL9943F1Z6
UDYAM-TN-11-0000905

SERVICE REPORT

Report ID: REP-D9A2A312

Date of Issue: 03/06/2026

Track ID: FSR-2026-00008

CUSTOMER INFORMATION

Company: Laser Tech Solutions Ltd
Contact: Robert Paulson
Mobile: +919876543210

EQUIPMENT SPECIFICATIONS

Brand / Maker: Maxphotonics
Model: MAX-C2000
Serial No: MAX-2KW-3312
Power Rating: 2kW

DIAGNOSTICS & FINDINGS

Customer Complaint: Deionized water leaking near output collimator boot seal.

Fault Found: Output collimator water seal gasket degraded.

Root Cause Analysis: Age-related thermal stress on standard silicone water ring.

REPAIR ACTIONS PERFORMED

Replaced coolant seals with high temperature Viton water gaskets.

SPARE PARTS REPLACED

No parts replaced. Service/Adjustments only.

MANDATORY VALIDATION TESTS

1. Output Power Test: PASS - 2.05kW output power stable
2. Stability Test: PASS - Nominal power ripple <0.8%
3. Burn-In Test: PASS - 2 hour run checked clean
4. Alarm Verification: PASS - Pressure switch closed
5. Temperature Test: PASS - Stable chiller coolant flow
6. Communication Test: PASS - Comm locks active

FINAL TESTING OUTCOME: PASS

Engineer In-Charge: Senior Engineer John Doe

Authorized Quality Control Signoff