

SIS Cause & Effect Matrix

Doc No. RB-4410-STD-CE-001 Rev B. Controlling document for safety instrumented functions (IEC 61511).

SIF	Cause (initiator)	Trip set point	Voting	Effect	SIL
SIF-3101	TT-3101 / TT-3102 SAG trunnion bearing temperature	TAHH 85 degC	1oo2	Stop ML-3101 GMD; stop feed CV-3101	SIL 1
SIF-3102	PT-3104 hydrostatic lift oil pressure	PALL 70 bar(g)	1oo1	Inhibit start / stop ML-3101	SIL 1
SIF-6101	PT-6103 tailings stage-3 discharge pressure	PAHH 38 bar(g)	2oo3	Trip PP-6101A/B/C	SIL 2