

Safety Data Sheet Summary - Quicklime / hydrated lime

Site summary for demonstration. Refer to the supplier SDS for the authoritative document.

SDS sections

Parameter	Value
1. Identification	Quicklime / hydrated lime; use: SL-4521 / TK-4521, pH modifier
CAS No.	1305-78-8 / 1305-62-0
Formula / type	CaO / Ca(OH) ₂
2. Hazards identification	Skin corrosion 1B / serious eye damage 1; exothermic with water (slaker)
4. First aid	Remove to fresh air; flush eyes and skin with water for 15 minutes; seek medical attention.
5. Fire fighting	Dry chemical, CO ₂ or foam. Do not use water jet on burning xanthate.
7. Handling and storage	Store cool and dry, away from acids and ignition sources; keep containers closed.
8. Exposure controls	Local exhaust ventilation; chemical goggles; nitrile gloves; respirator where exposure limits may be exceeded.