SINCE 1908 wessels company

RETURN MATERIAL AUTHORIZATION (RMA) REQUEST FORM

RMA REQ FORM
Ver. 2026 – 01

RMA#

Please complete this document in full, if able. Failure to include Order/Purchasing information may result in delayed processing or voided requests.
All information will be used to source your RMA request. Please complete carefully and accurately, revisions must be approved by Wessels prior to resubmittal.

RMA Requestor Contact information

Name: Jake Avorio E-mail: javorio@bornquist.com Phone: 773-467-4046

Please return completed form to: Customer_Service@westank.com

Order / Purchasing Information *(typically obtained by/through Vendor)*

Wessels Order #: *(or Purchase Order #, if Wessels order not known)*

B.I. PO# 1185025 (Wessels Order# 251726)

Date Shipped/Received:

6/1/26

Serial #/ National Board #: *(if multiple, please list each affected)*

Model / Type:

FX-500V NON-ASME EXPANSION TANK

Technical & Field Information *(typically obtained from end-user)*

This section is not required for all RMA's, but including this information may assist in diagnosing any end-user issues (bladder failures, leaks, etc.)

Quick Details *(mark all that apply)*

- ☐ No longer needed / ordered by mistake
- ■ Manufacturing Defect
- ☐ Tank has NOT been installed
- ■ Unit has been installed into a system (NOT active/commissioned), Install date: 9/1/26
- ☐ Unit has been installed into an active/commissioned system, Install date:

Installation-Specific Details *(complete all that may apply)*

Field Pre-charge of Unit: 0 PSI (53 PSI doesn't hold)

Unit contents: (i.e. Glycol, Potable water, etc.) Potable Water

Unit type/purpose: (i.e. filtration, expansion, overflow, etc.) Expansion

Maximum Operating Temperature of unit: 190

Maximum Pressure of unit/system: 65 PSI (operates at 55/65)

Water/fluid added to bladder during pre-charge process? ○ Yes ◉ No ○ N/A

Please provide a description of the RMA request below.
Be sure to include any photos are attached to the RMA request e-mail. Accurate information here may help our team determine the root cause.

FLANGE BOLT APPEARS TO HAVE PIERCED THE CHASSIS OF THE TANK & WILL NOT HOLD

If no issue is found, a 25% restocking fee will be assessed.
Submitted RMA form will typically be reviewed and responded to within 2 business days.
Ensure a copy of the RMA approval form is included with your shipment. Any shipment without paperwork is subject to refusal.
If water needs to be removed from a tank, use the lowest port drain fitting (a plug may need to be removed). If there is no drain plug, please drill a hole (as small as necessary) in the **bottom head**. If a hole is drilled in the shell, **the warranty may be voided and the RMA is subject to refusal**. Please notify the RMA team if a hole will be drilled in the head, as doing so may delay parts of the RMA process.